

## Purchase this vehicle with complete confidence!

**(888) 987-7788**  
sales@nicecarcompany.com

**NICE CAR COMPANY**

### Vehicle Certified by

Herman's Automotive  
3350 N. Holland-Sylvania Rd  
Toledo, OH 43615

### Extended Warrantys Available

12 Month / 15k Mile  
24 Month / 30k Mile  
36 Month / 36k Mile

Component	Mechanics Evaluation	Update Cost
-----------	----------------------	-------------

#### Engine

Engine Management Sensors	OEM – But still in very good condition	
Engine Mounts	OEM – But still in very good condition	
Ignition Coil	Good Condition	
Spark Plug Wires	Good Condition	
Spark Plugs	Good Condition	
Vacuum Hoses	OEM – But still in very good condition	
Air Filter	Good Condition	
Engine Oil & Filter	Replaced by Herman's Automotive	21.50

#### Transmission

4x4 Transfer Case	Not applicable to this vehicle	
Linkage	Not applicable to this vehicle	
Clutch	Not applicable to this vehicle	
Differential	Not applicable to this vehicle	
Shift Operation	Shift is precise – No apparent slippage	
Fluid	Fluid is clean and color is normal	

#### Brakes

ABS System	System operating normally	
Brake Lines	Good Condition	
Brake Hoses	Good Condition	
Wheel Speed Sensors	System operating normally	
Master Cylinder	Good Condition	
Wheel Hub Assembly	Good Condition	
Wheel Cylinders	Good Condition	
Brake Calipers	Good Condition	
Rear Rotors/Drums	Good Condition	
Front Rotors	Replaced by Herman's Automotive	181.83
Rear Pads/Shoes	60-70% of Estimated pad life remaining	
Front Pads	Replaced by Herman's Automotive	45.59

#### Steering & Suspension

Power Steering Pump	OEM – But still in very good condition	
Power Steering Rack	OEM – But still in very good condition	
Springs	OEM – But still in very good condition	
Ball Joints	Good Condition	
CV Joints & Boots	OEM – But still in very good condition	
Universal Joints	OEM – But still in very good condition	
Outer Tie Rods	Good Condition	
Inner Tie Rods	Good Condition	
Rear Struts/Shocks	OEM – But still in very good condition	
Front Struts/Shocks	OEM – But still in very good condition	
Steering Column	OEM – But still in very good condition	
Control Arm Bushings	OEM – But still in very good condition	
Stabilizer Bushings	OEM – But still in very good condition	
Stabilizer Links	OEM – But still in very good condition	

#### Exhaust System

Tail Pipe	OEM – But still in very good condition	
Resonator	OEM – But still in very good condition	
Muffler	OEM – But still in very good condition	
Catalytic Converter	OEM – But still in very good condition	
Exhaust Pipe	OEM – But still in very good condition	

#### Heating & Cooling System

Air Conditioning	System operating normally	
Heater Hoses	OEM – But still in very good condition	
Heater Performance	System operating normally	
Blower Controls	System operating normally	
Fan	OEM – But still in very good condition	
Radiator Hoses/Cap	Good Condition	
Radiator	OEM – But still in very good condition	
Water Pump	OEM – But still in very good condition	
Belt Tensioner	OEM – But still in very good condition	
Belts	Good Condition	
Antifreeze	Fluid is clean and color is normal	

### Completed Updates:

Tire Rotation & Wheel Balance	30.00
Front Rotors	181.83
Front Pads	45.59
Engine Oil & Filter	21.50
Vehicle Inspection Fee	50

**Total Reconditioning Costs: \$328.92**

Component	Mechanics Evaluation	Update Cost
-----------	----------------------	-------------

#### Starting / Charging System

Alternator / Regulator	System operating normally	
Starter	System operating normally	
Battery	Good Condition	

#### Fuel System

Fuel Injectors	System operating normally	
Fuel Pump	System operating normally	
Fuel Filter	Good Condition	
Fuel Lines	System is sound with no apparent leaks	
Fuel Tank	System is sound with no apparent leaks	

#### Electrical System

Dome Lights	All Bulbs and switches working properly	
Dash Lights	All Bulbs and switches working properly	
Turn Signals	All Bulbs and switches working properly	
Dimmer Switch	All Bulbs and switches working properly	
Brake Lights	All Bulbs and switches working properly	
Tail Lights	All Bulbs and switches working properly	
Head Lights	All Bulbs and switches working properly	
Keyless Entry	System operating normally	
Cruise Control	System operating normally	
DVD Entertainment	Not applicable to this vehicle	
Backup Sensors	Not applicable to this vehicle	
Backup Camera	Not applicable to this vehicle	
GPS/Navigation	Not applicable to this vehicle	
Power Mirrors	System operating normally	
Power Liftgate	Not applicable to this vehicle	
Power Sliding Door(s)	Not applicable to this vehicle	
Power Sunroof	Not applicable to this vehicle	
Power Trunk	Not applicable to this vehicle	
Power Seat(s)	Switches and Motors Operating Normally	
Power Locks	Switches and Motors Operating Normally	
Power Windows	Switches and Motors Operating Normally	
Horn	System operating normally	
CD Player	System operating normally	
Radio	System operating normally	
Windshield Washers	System operating normally	
Windshield Wipers	System operating normally	
License Plate Light	All Bulbs and switches working properly	
Backup Lights	All Bulbs and switches working properly	
Gauges / Indicators	System operating normally	

#### Miscellaneous

Wiper Blades	Good Condition	
Spare Tire & Jack	System operating normally	
Alignment	System operating normally	
Tire Pressure	Normal Condition	
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	30.00
Rear Tires	70-80% of Tread life remaining	
Front Tires	70-80% of Tread life remaining	

**\*\*\* OEM - Original Equipment from the Manufacturer**