

## Purchase this vehicle with complete confidence!

**(888) 987-7788**  
sales@nicecarcompany.com

**NICE CAR COMPANY**

### Vehicle Certified by

Herman's Automotive  
3350 N. Holland-Sylvania Rd  
Toledo, OH 43615

### Extended Warrantys Available

12 Month / 15k Mile  
24 Month / 30k Mile  
36 Month / 36k Mile

Component	Mechanics Evaluation	Update Cost
-----------	----------------------	-------------

#### Engine

Engine Oil & Filter	Replaced Recently by Previous Owner
Air Filter	Good Condition
Vacuum Hoses	OEM – But still in very good condition
Spark Plugs	Good Condition
Spark Plug Wires	Good Condition
Ignition Coil	Good Condition
Engine Mounts	OEM – But still in very good condition
Engine Management Sensors	OEM – But still in very good condition

#### Transmission

Fluid	Fluid is clean and color is normal
Shift Operation	Shift is precise – No apparent slippage
Differential	Not applicable to this vehicle
Clutch	Not applicable to this vehicle
Linkage	Not applicable to this vehicle
4x4 Transfer Case	Not applicable to this vehicle

#### Brakes

Front Pads	Replaced Recently by Previous Owner
Rear Pads/Shoes	Replaced Recently by Previous Owner
Front Rotors	Replaced Recently by Previous Owner
Rear Rotors/Drums	Replaced Recently by Previous Owner
Brake Calipers	Good Condition
Wheel Cylinders	Good Condition
Wheel Hub Assembly	Good Condition
Master Cylinder	Good Condition
Wheel Speed Sensors	System operating normally
Brake Hoses	Good Condition
Brake Lines	Good Condition
ABS System	System operating normally

#### Steering & Suspension

Stabilizer Links	OEM – But still in very good condition
Stabilizer Bushings	OEM – But still in very good condition
Control Arm Bushings	OEM – But still in very good condition
Steering Column	OEM – But still in very good condition
Front Struts/Shocks	OEM – But still in very good condition
Rear Struts/Shocks	OEM – But still in very good condition
Inner Tie Rods	Good Condition
Outer Tie Rods	Good Condition
Universal Joints	OEM – But still in very good condition
CV Joints & Boots	OEM – But still in very good condition
Ball Joints	Good Condition
Springs	OEM – But still in very good condition
Power Steering Rack	OEM – But still in very good condition
Power Steering Pump	OEM – But still in very good condition

#### Exhaust System

Exhaust Pipe	OEM – But still in very good condition
Catalytic Converter	OEM – But still in very good condition
Muffler	OEM – But still in very good condition
Resonator	OEM – But still in very good condition
Tail Pipe	OEM – But still in very good condition

#### Heating & Cooling System

Antifreeze	Fluid is clean and color is normal
Belts	Good Condition
Belt Tensioner	OEM – But still in very good condition
Water Pump	OEM – But still in very good condition
Radiator	OEM – But still in very good condition
Radiator Hoses/Cap	Good Condition
Fan	OEM – But still in very good condition
Blower Controls	System operating normally
Heater Performance	System operating normally
Heater Hoses	OEM – But still in very good condition
Air Conditioning	System operating normally

### Completed Updates:

Front Tires	225
Rear Tires	225
Vehicle Inspection Fee	50

**Total Reconditioning Costs: \$500.00**

Component	Mechanics Evaluation	Update Cost
-----------	----------------------	-------------

#### Starting / Charging System

Battery	Good Condition
Starter	System operating normally
Alternator / Regulator	System operating normally

#### Fuel System

Fuel Tank	System is sound with no apparent leaks
Fuel Lines	System is sound with no apparent leaks
Fuel Filter	Good Condition
Fuel Pump	System operating normally
Fuel Injectors	System operating normally

#### Electrical System

Windshield Wipers	System operating normally
Windshield Washers	System operating normally
Radio	System operating normally
CD Player	System operating normally
Horn	System operating normally
Power Windows	Switches and Motors Operating Normally
Power Locks	Switches and Motors Operating Normally
Power Seat(s)	Switches and Motors Operating Normally
Power Trunk	Switches and Motors Operating Normally
Power Sunroof	Not applicable to this vehicle
Power Sliding Door(s)	Not applicable to this vehicle
Power Liftgate	Not applicable to this vehicle
Power Mirrors	System operating normally
GPS/Navigation	Not applicable to this vehicle
Backup Camera	Not applicable to this vehicle
Backup Sensors	Not applicable to this vehicle
DVD Entertainment	Not applicable to this vehicle
Cruise Control	System operating normally
Keyless Entry	System operating normally
Head Lights	All Bulbs and switches working properly
Tail Lights	All Bulbs and switches working properly
Brake Lights	All Bulbs and switches working properly
Dimmer Switch	All Bulbs and switches working properly
Turn Signals	All Bulbs and switches working properly
Dash Lights	All Bulbs and switches working properly
Dome Lights	All Bulbs and switches working properly
License Plate Light	All Bulbs and switches working properly
Backup Lights	All Bulbs and switches working properly
Gauges / Indicators	System operating normally

#### Miscellaneous

Front Tires	Replaced Recently by Previous Owner	225
Rear Tires	Replaced Recently by Previous Owner	225
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	
Tire Pressure	Normal Condition	
Alignment	System operating normally	
Spare Tire & Jack	System operating normally	
Wiper Blades	Good Condition	

**\*\*\* OEM - Original Equipment from the Manufacturer**