

## Purchase this vehicle with complete confidence!

### Vehicle Certified by

Herman's Automotive  
3350 N. Holland-Sylvania Rd  
Toledo, OH 43615

### Extended Warrantys Available

12 Month / 15k Mile  
24 Month / 30k Mile  
36 Month / 36k Mile

Component	Mechanics Evaluation	Update Cost
-----------	----------------------	-------------

#### Engine

Engine Management Sensors	OEM – But still in very good condition	
Engine Mounts	OEM – But still in very good condition	
Ignition Coil	Good Condition	
Spark Plug Wires	Good Condition	
Spark Plugs	Good Condition	
Vacuum Hoses	OEM – But still in very good condition	
Air Filter	Good Condition	
Engine Oil & Filter	Replaced by Herman's Automotive	49.45

#### Transmission

4x4 Transfer Case	Not applicable to this vehicle
Linkage	Not applicable to this vehicle
Clutch	Not applicable to this vehicle
Differential	Not applicable to this vehicle
Shift Operation	Shift is precise – No apparent slippage
Fluid	Fluid is clean and color is normal

#### Brakes

ABS System	System operating normally	
Brake Lines	Good Condition	
Brake Hoses	Good Condition	
Wheel Speed Sensors	System operating normally	
Master Cylinder	Good Condition	
Wheel Hub Assembly	Good Condition	
Wheel Cylinders	Good Condition	
Brake Calipers	Good Condition	
Rear Rotors/Drums	Replaced by Herman's Automotive	181.58
Front Rotors	Replaced by Herman's Automotive	189.18
Rear Pads/Shoes	Replaced by Herman's Automotive	4559
Front Pads	Replaced by Herman's Automotive	45.59

#### Steering & Suspension

Power Steering Pump	OEM – But still in very good condition
Power Steering Rack	OEM – But still in very good condition
Springs	OEM – But still in very good condition
Ball Joints	Good Condition
CV Joints & Boots	OEM – But still in very good condition
Universal Joints	OEM – But still in very good condition
Outer Tie Rods	Good Condition
Inner Tie Rods	Good Condition
Rear Struts/Shocks	OEM – But still in very good condition
Front Struts/Shocks	OEM – But still in very good condition
Steering Column	OEM – But still in very good condition
Control Arm Bushings	OEM – But still in very good condition
Stabilizer Bushings	OEM – But still in very good condition
Stabilizer Links	OEM – But still in very good condition

#### Exhaust System

Tail Pipe	OEM – But still in very good condition
Resonator	OEM – But still in very good condition
Muffler	OEM – But still in very good condition
Catalytic Converter	OEM – But still in very good condition
Exhaust Pipe	OEM – But still in very good condition

#### Heating & Cooling System

Air Conditioning	System operating normally
Heater Hoses	OEM – But still in very good condition
Heater Performance	System operating normally
Blower Controls	System operating normally
Fan	OEM – But still in very good condition
Radiator Hoses/Cap	Good Condition
Radiator	OEM – But still in very good condition
Water Pump	OEM – But still in very good condition
Belt Tensioner	OEM – But still in very good condition
Belts	Good Condition
Antifreeze	Fluid is clean and color is normal

(888) 987-7788  
sales@nicecarcompany.com

NICE CAR COMPANY

### Completed Updates:

Tire Rotation & Wheel Balance	30.00
Rear Rotors/Drums	181.58
Front Rotors	189.18
Rear Pads/Shoes	4559
Front Pads	45.59
Engine Oil & Filter	49.45
Vehicle Inspection Fee	50

**Total Reconditioning Costs: \$5,104.80**

Component	Mechanics Evaluation	Update Cost
-----------	----------------------	-------------

#### Starting / Charging System

Alternator / Regulator	System operating normally
Starter	System operating normally
Battery	Good Condition

#### Fuel System

Fuel Injectors	System operating normally
Fuel Pump	System operating normally
Fuel Filter	Good Condition
Fuel Lines	System is sound with no apparent leaks
Fuel Tank	System is sound with no apparent leaks

#### Electrical System

Turn Signals	All Bulbs and switches working properly
Dimmer Switch	All Bulbs and switches working properly
Brake Lights	All Bulbs and switches working properly
Tail Lights	All Bulbs and switches working properly
Head Lights	All Bulbs and switches working properly
Keyless Entry	System operating normally
Cruise Control	System operating normally
DVD Entertainment	Not applicable to this vehicle
Backup Sensors	Not applicable to this vehicle
Backup Camera	Not applicable to this vehicle
GPS/Navigation	Not applicable to this vehicle
Power Mirrors	System operating normally
Power Liftgate	Not applicable to this vehicle
Power Sliding Door(s)	Not applicable to this vehicle
Power Sunroof	Not applicable to this vehicle
Power Trunk	Switches and Motors Operating Normally
Power Seat(s)	Not applicable to this vehicle
Power Locks	Switches and Motors Operating Normally
Power Windows	Switches and Motors Operating Normally
Horn	System operating normally
CD Player	Not applicable to this vehicle
Radio	System operating normally
Windshield Washers	System operating normally
Windshield Wipers	System operating normally
Dash Lights	All Bulbs and switches working properly
Dome Lights	All Bulbs and switches working properly
License Plate Light	All Bulbs and switches working properly
Backup Lights	All Bulbs and switches working properly
Gauges / Indicators	System operating normally

#### Miscellaneous

Wiper Blades	Good Condition	
Spare Tire & Jack	System operating normally	
Alignment	System operating normally	
Tire Pressure	Normal Condition	
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	30.00
Rear Tires	70-80% of Tread life remaining	
Front Tires	70-80% of Tread life remaining	

**\*\*\* OEM - Original Equipment from the Manufacturer**