## Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

## **Extended Warrantys Available**

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component Mechanics Evaluation Update Cost

Engine

Engine Management Sensors OEM – But still in very good condition
Engine Mounts OEM – But still in very good condition

Ignition Coil Good Condition
Spark Plug Wires Good Condition
Spark Plugs Good Condition

Vacuum Hoses OEM – But still in very good condition

Air Filter Good Condition

Engine Oil & Filter Replaced by Herman's Automotive 66.95

**Transmission** 

 4x4 Transfer Case
 Not applicable to this vehicle

 Linkage
 Not applicable to this vehicle

 Clutch
 Not applicable to this vehicle

 Differential
 Not applicable to this vehicle

 Shift Operation
 Shift is precise – No apparent slippage

 Fluid
 Fluid is clean and color is normal

**Brakes** 

ABS System System operating normally

Brake Lines Good Condition
Brake Hoses Good Condition

Wheel Speed Sensors System operating normally

Master CylinderGood ConditionWheel Hub AssemblyGood ConditionWheel CylindersGood ConditionBrake CalipersGood ConditionRear Rotors/DrumsGood ConditionFront RotorsGood Condition

Rear Pads/Shoes 70-80% of Estimated pad life remaining Front Pads 70-80% of Estimated pad life remaining

Steering & Suspension

Power Steering Pump OEM – But still in very good condition
Power Steering Rack OEM – But still in very good condition
Springs OEM – But still in very good condition

Ball Joints Good Condition

CV Joints & Boots OEM – But still in very good condition
Universal Joints OEM – But still in very good condition

Outer Tie Rods Good Condition
Inner Tie Rods Good Condition

Rear Struts/Shocks

Front Struts/Shocks

OEM – But still in very good condition

Steering Column

Control Arm Bushings

OEM – But still in very good condition

Stabilizer Bushings

OEM – But still in very good condition

OEM – But still in very good condition

OEM – But still in very good condition

**Exhaust System** 

Tail Pipe OEM – But still in very good condition
Resonator OEM – But still in very good condition
Muffler OEM – But still in very good condition
Catalytic Converter OEM – But still in very good condition
Exhaust Pipe OEM – But still in very good condition

Heating & Cooling System

Air Conditioning System operating normally

Heater Hoses OEM – But still in very good condition

Heater Performance System operating normally Blower Controls System operating normally

Fan OEM – But still in very good condition

Radiator Hoses/Cap Good Condition

Radiator OEM – But still in very good condition
Water Pump OEM – But still in very good condition
Belt Tensioner OEM – But still in very good condition

Belts Good Condition

Antifreeze Fluid is clean and color is normal

(888) 987-7788 sales@nicecarcompany.com

**NICE CAR COMPANY** 

**Completed Updates:** 

Tire Rotation & Wheel Balance 30.00
Engine Oil & Filter 66.95
Vehicle Inspection Fee 50

Total Reconditioning Costs: \$146.95

Component Mechanics Evaluation Update Cost

Starting / Charging System

Alternator / Regulator System operating normally Starter System operating normally

Battery Good Condition

**Fuel System** 

Fuel Injectors System operating normally Fuel Pump System operating normally

Fuel Filter Good Condition

Fuel Lines System is sound with no apparent leaks
Fuel Tank System is sound with no apparent leaks

**Electrical System** 

Backup Lights All Bulbs and switches working properly License Plate Light All Bulbs and switches working properly Dome Lights All Bulbs and switches working properly Dash Lights All Bulbs and switches working properly All Bulbs and switches working properly Turn Signals Dimmer Switch All Bulbs and switches working properly All Bulbs and switches working properly **Brake Lights** All Bulbs and switches working properly Tail Lights Head Lights All Bulbs and switches working properly

Keyless Entry System operating normally Cruise Control System operating normally **DVD** Entertainment Not applicable to this vehicle Not applicable to this vehicle Backup Sensors Backup Camera System operating normally GPS/Navigation Not applicable to this vehicle Power Mirrors System operating normally Power Liftgate Not applicable to this vehicle Power Sliding Door(s) Not applicable to this vehicle Power Sunroof Not applicable to this vehicle

Power Trunk Switches and Motors Operating Normally
Power Seat(s) Switches and Motors Operating Normally
Power Locks Switches and Motors Operating Normally
Power Windows Switches and Motors Operating Normally

Horn System operating normally
CD Player Not applicable to this vehicle
Radio System operating normally
Windshield Washers System operating normally
Windshield Wipers System operating normally
Gauges / Indicators System operating normally

Miscellaneous

Wiper Blades Good Condition
Spare Tire & Jack System operating normally
Alignment System operating normally

Tire Pressure Normal Condition

Tire Rotation & Wheel Balance Serviced by Herman's Automotive Rear Tires 70-80% of Tread life remaining

Front Tires 70-80% of Tread life remaining

\*\*\* OEM - Original Equipment from the Manufacturer

30.00