# Purchase this vehicle with complete confidence!

### Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

**Extended Warrantys Available** 12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation	Update Cost
Engine		
Engine Oil & Filter	Replaced by Herman's Automotive	77.92
Air Filter	Good Condition	
Vacuum Hoses	OEM – But still in very good condition	on
Spark Plugs	Good Condition	
Spark Plug Wires	Good Condition	
Ignition Coil	Good Condition	
Engine Mounts	OEM – But still in very good condition	on
Engine Management Sensors	OEM – But still in very good condition	on
Transmission		
Fluid	Fluid is clean and color is normal	
Shift Operation	Shift is precise - No apparent slippa	age
Differential	Not applicable to this vehicle	
Clutch	Not applicable to this vehicle	
Linkage	Not applicable to this vehicle	
4x4 Transfer Case	Not applicable to this vehicle	
Brakes		
Front Pads	70-80% of Estimated pad life remai	ning
Rear Pads/Shoes	70-80% of Estimated pad life remai	ning
Front Rotors	Good Condition	
Rear Rotors/Drums	Good Condition	
Brake Calipers	Good Condition	
Wheel Cylinders	Good Condition	
Wheel Hub Assembly	Good Condition	
Master Cylinder	Good Condition	
Wheel Speed Sensors	System operating normally	
Brake Hoses	Good Condition	
Brake Lines	Good Condition	
ABS System	System operating normally	
Steering & Suspension		
Stabilizer Links	OEM - But still in very good condition	on
Stabilizer Bushings	OEM - But still in very good condition	on
Control Arm Bushings	OEM - But still in very good condition	on
Steering Column	OEM - But still in very good condition	on
Front Struts/Shocks	OEM - But still in very good condition	on
Rear Struts/Shocks	OEM - But still in very good condition	on
Inner Tie Rods	Good Condition	
Outer Tie Rods	Good Condition	
Universal Joints	OEM - But still in very good condition	on
CV Joints & Boots	OEM – But still in very good condition	
Ball Joints	Good Condition	
Springs	OEM – But still in very good condition	on
Power Steering Rack	OEM – But still in very good condition	
Power Steering Pump	OEM – But still in very good condition	
Exhaust System		
Exhaust Pipe	OEM – But still in very good condition	on
Catalytic Converter	OEM – But still in very good condition	
Muffler	OEM – But still in very good condition	
		-

#### Tail Pipe

Resonator

Belts

Fan

Heating & Cooling System Antifreeze Fluid is clean and color is normal Good Condition OEM - But still in very good condition Belt Tensioner Water Pump OEM - But still in very good condition OEM - But still in very good condition Radiator Radiator Hoses/Cap Good Condition OEM - But still in very good condition Blower Controls System operating normally Heater Performance System operating normally OEM - But still in very good condition Heater Hoses Air Conditioning System operating normally

OEM – But still in very good condition

OEM - But still in very good condition



# NICE CAR COMPANY

								-	_
ิดท	ico	ca	rco	m	na	m	y.com		
ee 1	ice	ca	100		Pa		<i>y.</i> com		

Completed Updates:					
Engine Oil & Filter	77.92				
Tire Rotation & Wheel Balance	40.00				
Vehicle Inspection Fee	50				
Total Reconditioning Costs:	\$167.92				

Component	Mechanics Evaluation Upda	ate Cost
Starting / Charging System		
Battery	Good Condition	
Starter	System operating normally	
Alternator / Regulator	System operating normally	
-		
Fuel System	System is sound with no apparent looks	
Fuel Lines	System is sound with no apparent leaks	
Fuel Filter	System is sound with no apparent leaks Good Condition	
Fuel Pump	System operating normally	
Fuel Injectors	System operating normally	
Electrical System		
Windshield Wipers	System operating normally	
Windshield Washers	System operating normally	
Radio	System operating normally	
CD Player	System operating normally	
Horn	System operating normally	
Power Windows	Switches and Motors Operating Normally	у
Power Locks	Switches and Motors Operating Normally	у
Power Seat(s)	Switches and Motors Operating Normally	у
Power Trunk	Not applicable to this vehicle	
Power Sunroof	Not applicable to this vehicle	
Power Sliding Door(s)	Not applicable to this vehicle	
Power Liftgate	Not applicable to this vehicle	
Power Mirrors	System operating normally	
GPS/Navigation	System operating normally	
Backup Camera	System operating normally	
Backup Sensors	System operating normally	
DVD Entertainment	Not applicable to this vehicle	
Cruise Control	System operating normally	
Keyless Entry	Not applicable to this vehicle	
Head Lights	All Bulbs and switches working properly	
Tail Lights	All Bulbs and switches working properly	
Brake Lights	All Bulbs and switches working properly	
Dimmer Switch	All Bulbs and switches working properly	
Turn Signals	All Bulbs and switches working properly	
Dash Lights	All Bulbs and switches working properly	
Dome Lights	All Bulbs and switches working properly	
License Plate Light	All Bulbs and switches working properly	
Backup Lights	All Bulbs and switches working properly	
Gauges / Indicators	System operating normally	
Miscellaneous		
Front Tires	70-80% of Tread life remaining	
Rear Tires	70-80% of Tread life remaining	
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	40.00
	Serviced by Herman's Automotive	-0.00

	10-00 % OF Fread life fernaliting	
Rear Tires	70-80% of Tread life remaining	
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	40.00
Tire Pressure	Normal Condition	
Alignment	System operating normally	
Spare Tire & Jack	System operating normally	
Wiper Blades	Good Condition	

### \*\*\* OEM - Original Equipment from the Manufacturer