Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component Mechanics Evaluation Update Cost

Ε	n	g	ir	ne	

Engine Management Sensors OEM – But still in very good condition
Engine Mounts OEM – But still in very good condition

Ignition Coil Good Condition
Spark Plugs Good Condition
Spark Plugs Good Condition

Spark Plugs Good Condition

Vacuum Hoses OEM – But still in very good condition

Air Filter Replaced by Herman's Automotive 28.99
Engine Oil & Filter Replaced by Herman's Automotive 30.95

Transmission

 4x4 Transfer Case
 Not applicable to this vehicle

 Linkage
 Not applicable to this vehicle

 Clutch
 Not applicable to this vehicle

 Differential
 Not applicable to this vehicle

 Shift Operation
 Shift is precise – No apparent slippage

 Fluid
 Fluid is clean and color is normal

Brakes

ABS System System operating normally

Brake Lines Good Condition
Brake Hoses Good Condition

Wheel Speed Sensors

Master Cylinder

Wheel Hub Assembly

Wheel Cylinders

Good Condition

Rear Rotors/Drums

Good Condition

Rear Pads/Shoes 70-80% of Estimated pad life remaining Front Pads 70-80% of Estimated pad life remaining

Good Condition

Steering & Suspension

Front Rotors

Power Steering Pump OEM – But still in very good condition
Power Steering Rack OEM – But still in very good condition
Springs OEM – But still in very good condition

Ball Joints Good Condition

CV Joints & Boots OEM – But still in very good condition
Universal Joints OEM – But still in very good condition

Outer Tie Rods Good Condition

Inner Tie Rods Good Condition

Rear Struts/Shocks

Front Struts/Shocks

OEM – But still in very good condition

Steering Column

Control Arm Bushings

OEM – But still in very good condition

OEM – But still in very good condition

OEM – But still in very good condition

Stabilizer Bushings

OEM – But still in very good condition

Stabilizer Links

OEM – But still in very good condition

Exhaust System

Tail Pipe OEM – But still in very good condition
Resonator OEM – But still in very good condition
Muffler OEM – But still in very good condition
Catalytic Converter OEM – But still in very good condition
Exhaust Pipe OEM – But still in very good condition

Heating & Cooling System

Air Conditioning System operating normally

Heater Hoses OEM – But still in very good condition

Heater Performance System operating normally Blower Controls System operating normally

Fan OEM – But still in very good condition

Radiator Hoses/Cap Good Condition

Radiator

OEM – But still in very good condition

Water Pump

OEM – But still in very good condition

Belt Tensioner

OEM – But still in very good condition

Belts Good Condition

Antifreeze Fluid is clean and color is normal

(888) 987-7788

sales@nicecarcompany.com

NICE CAR COMPANY

Completed Updates:

Tire Rotation & Wheel Balance 40.00
Air Filter 28.99
Engine Oil & Filter 30.95
Vehicle Inspection Fee 50

Total Reconditioning Costs: \$149.94

Component Mechanics Evaluation Update Cost

Starting / Charging System

Alternator / Regulator System operating normally
Starter System operating normally
Battery Good Condition

Fuel System

Fuel Injectors System operating normally Fuel Pump System operating normally

Fuel Filter Good Condition

Fuel Lines System is sound with no apparent leaks
Fuel Tank System is sound with no apparent leaks

Electrical System

License Plate Light All Bulbs and switches working properly Dome Lights All Bulbs and switches working properly Dash Lights All Bulbs and switches working properly All Bulbs and switches working properly Turn Signals All Bulbs and switches working properly Dimmer Switch **Brake Lights** All Bulbs and switches working properly Tail Lights All Bulbs and switches working properly All Bulbs and switches working properly Head Lights

Kevless Entry System operating normally Cruise Control System operating normally **DVD** Entertainment Not applicable to this vehicle Backup Sensors Not applicable to this vehicle Backup Camera System operating normally GPS/Navigation Not applicable to this vehicle Power Mirrors System operating normally Power Liftgate Not applicable to this vehicle

Power Sunroof Not applicable to this vehicle
Power Trunk Not applicable to this vehicle
Power Seat(s) Switches and Motors Operating Normally
Power Locks Switches and Motors Operating Normally

Not applicable to this vehicle

Power Windows
Switches and Motors Operating Normally
Horn
System operating normally
CD Player
Not applicable to this vehicle
Radio
System operating normally
Windshield Washers
System operating normally
Windshield Wipers
System operating normally

Backup Lights All Bulbs and switches working properly

Gauges / Indicators System operating normally

Miscellaneous

Front Tires

Power Sliding Door(s)

Wiper Blades Good Condition
Spare Tire & Jack System operating normally
Alignment System operating normally

Tire Pressure Normal Condition

Tire Rotation & Wheel Balance Serviced by Herman's Automotive Rear Tires 70-80% of Tread life remaining

*** OEM - Original Equipment from the Manufacturer

70-80% of Tread life remaining

40.00