

# Purchase this vehicle with complete confidence!

**(888) 987-7788**  
sales@nicecarcompany.com

**NICE CAR COMPANY**

## Vehicle Certified by

Herman's Automotive  
3350 N. Holland-Sylvania Rd  
Toledo, OH 43615

## Extended Warrantys Available

12 Month / 15k Mile  
24 Month / 30k Mile  
36 Month / 36k Mile

Component	Mechanics Evaluation	Update Cost
-----------	----------------------	-------------

### Engine

Engine Oil & Filter	Replaced by Herman's Automotive	
Air Filter	Good Condition	
Vacuum Hoses	OEM – But still in very good condition	
Spark Plugs	Good Condition	
Spark Plug Wires	Good Condition	
Ignition Coil	Good Condition	
Engine Mounts	OEM – But still in very good condition	
Engine Management Sensors	OEM – But still in very good condition	

### Transmission

Fluid	Fluid is clean and color is normal	
Shift Operation	Shift is precise – No apparent slippage	
Differential	Not applicable to this vehicle	
Clutch	Not applicable to this vehicle	
Linkage	Not applicable to this vehicle	
4x4 Transfer Case	Not applicable to this vehicle	

### Brakes

Front Pads	70-80% of Estimated pad life remaining	
Rear Pads/Shoes	70-80% of Estimated pad life remaining	
Front Rotors	Good Condition	
Rear Rotors/Drums	Good Condition	
Brake Calipers	Good Condition	
Wheel Cylinders	Good Condition	
Wheel Hub Assembly	Good Condition	
Master Cylinder	Good Condition	
Wheel Speed Sensors	System operating normally	
Brake Hoses	Good Condition	
Brake Lines	Good Condition	
ABS System	System operating normally	

### Steering & Suspension

Stabilizer Links	OEM – But still in very good condition	
Stabilizer Bushings	OEM – But still in very good condition	
Control Arm Bushings	OEM – But still in very good condition	
Steering Column	OEM – But still in very good condition	
Front Struts/Shocks	OEM – But still in very good condition	
Rear Struts/Shocks	OEM – But still in very good condition	
Inner Tie Rods	Good Condition	
Outer Tie Rods	Good Condition	
Universal Joints	OEM – But still in very good condition	
CV Joints & Boots	OEM – But still in very good condition	
Ball Joints	Good Condition	
Springs	OEM – But still in very good condition	
Power Steering Rack	OEM – But still in very good condition	
Power Steering Pump	OEM – But still in very good condition	

### Exhaust System

Exhaust Pipe	OEM – But still in very good condition	
Catalytic Converter	OEM – But still in very good condition	
Muffler	OEM – But still in very good condition	
Resonator	OEM – But still in very good condition	
Tail Pipe	OEM – But still in very good condition	

### Heating & Cooling System

Antifreeze	Fluid is clean and color is normal	
Belts	Good Condition	
Belt Tensioner	OEM – But still in very good condition	
Water Pump	OEM – But still in very good condition	
Radiator	OEM – But still in very good condition	
Radiator Hoses/Cap	Good Condition	
Fan	OEM – But still in very good condition	
Blower Controls	System operating normally	
Heater Performance	System operating normally	
Heater Hoses	OEM – But still in very good condition	
Air Conditioning	System operating normally	

## Completed Updates:

Vehicle Inspection Fee 50  
**Total Reconditioning Costs: \$50.00**

Component	Mechanics Evaluation	Update Cost
-----------	----------------------	-------------

### Starting / Charging System

Battery	Good Condition	
Starter	System operating normally	
Alternator / Regulator	System operating normally	

### Fuel System

Fuel Tank	System is sound with no apparent leaks	
Fuel Lines	System is sound with no apparent leaks	
Fuel Filter	Good Condition	
Fuel Pump	System operating normally	
Fuel Injectors	System operating normally	

### Electrical System

Windshield Wipers	System operating normally
Windshield Washers	System operating normally
Radio	System operating normally
CD Player	Not applicable to this vehicle
Horn	System operating normally
Power Windows	Switches and Motors Operating Normally
Power Locks	Switches and Motors Operating Normally
Power Seat(s)	Switches and Motors Operating Normally
Power Trunk	Not applicable to this vehicle
Power Sunroof	Switches and Motors Operating Normally
Power Sliding Door(s)	Not applicable to this vehicle
Power Liftgate	System operating normally
Power Mirrors	System operating normally
GPS/Navigation	Not applicable to this vehicle
Backup Camera	System operating normally
Backup Sensors	System operating normally
DVD Entertainment	Not applicable to this vehicle
Cruise Control	System operating normally
Keyless Entry	System operating normally
Head Lights	All Bulbs and switches working properly
Tail Lights	All Bulbs and switches working properly
Brake Lights	All Bulbs and switches working properly
Dimmer Switch	All Bulbs and switches working properly
Turn Signals	All Bulbs and switches working properly
Dash Lights	All Bulbs and switches working properly
Dome Lights	All Bulbs and switches working properly
License Plate Light	All Bulbs and switches working properly
Backup Lights	All Bulbs and switches working properly
Gauges / Indicators	System operating normally

### Miscellaneous

Front Tires	70-80% of Tread life remaining
Rear Tires	70-80% of Tread life remaining
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive
Tire Pressure	Normal Condition
Alignment	System operating normally
Spare Tire & Jack	System operating normally
Wiper Blades	Good Condition

**\*\*\* OEM - Original Equipment from the Manufacturer**