Purchase this vehicle with complete confidence!

Vehic	le	Ce	ertifi	ed	by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available 12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation U	pdate Cost
Engine		
Engine Management Sensors	OEM – But still in very good condition)
Engine Mounts	OEM – But still in very good condition	ı
Ignition Coil	Good Condition	
Spark Plug Wires	Good Condition	
Spark Plugs	Good Condition	
Vacuum Hoses	OEM - But still in very good condition	1
Air Filter	Replaced by Herman's Automotive	29.99
Engine Oil & Filter	Replaced by Herman's Automotive	41.96
Transmission		
4x4 Transfer Case	Not applicable to this vehicle	
Linkage	Not applicable to this vehicle	
Clutch	Not applicable to this vehicle	
Differential	Not applicable to this vehicle	
Shift Operation	Shift is precise – No apparent slippag	e
Fluid	Fluid is clean and color is normal	
Brakes		
ABS System	System operating normally	
Brake Lines	Good Condition	
Brake Hoses	Good Condition	
Wheel Speed Sensors	System operating normally	
Master Cylinder	Good Condition	
Wheel Hub Assembly	Good Condition	
Wheel Cylinders	Good Condition	
Brake Calipers	Good Condition	
Rear Rotors/Drums	Good Condition	
Front Rotors	Replaced by Herman's Automotive	244.98
Rear Pads/Shoes	70-80% of Estimated pad life remaini	•
Front Pads	Replaced by Herman's Automotive	69.99
Steering & Suspension		
Power Steering Pump	OEM – But still in very good condition	
Power Steering Rack	OEM – But still in very good condition	
Springs	OEM – But still in very good condition	1
Ball Joints	Good Condition	
CV Joints & Boots	OEM – But still in very good condition	
Universal Joints	OEM – But still in very good condition	1
Outer Tie Rods	Good Condition	
Inner Tie Rods	Good Condition	
Rear Struts/Shocks	OEM – But still in very good condition	
Front Struts/Shocks	OEM – But still in very good condition	
Steering Column	OEM – But still in very good condition	
Control Arm Bushings	OEM – But still in very good condition	
Stabilizer Bushings	OEM – But still in very good condition	
Stabilizer Links	OEM – But still in very good condition	I
Exhaust System		
Tail Pipe	OEM – But still in very good condition	
Resonator	OEM – But still in very good condition	1

Muffler	
Catalytic Converter	
Exhaust Pipe	

	OEM – But still in very good condition
er	OEM – But still in very good condition
	OEM – But still in very good condition

Heating & Cooling System

Air Conditioning	System operating normally
Heater Hoses	OEM – But still in very good condition
Heater Performance	System operating normally
Blower Controls	System operating normally
Fan	OEM – But still in very good condition
Radiator Hoses/Cap	Good Condition
Radiator	OEM – But still in very good condition
Water Pump	OEM – But still in very good condition
Belt Tensioner	OEM – But still in very good condition
Belts	Good Condition
Antifreeze	Fluid is clean and color is normal



NICE CAR COMPANY

Completed Updates:		
Wiper Blades	21.98	
Front Rotors	244.98	
Front Pads	69.99	
Air Filter	29.99	
Engine Oil & Filter	41.96	
Vehicle Inspection Fee	50	
Total Reconditioning Costs:	\$458.90	

Component	Mechanics Evaluation U	pdate Cost
Starting / Charging System		
Alternator / Regulator	System operating normally	
Starter	System operating normally	
Battery	Good Condition	
Fuel System		
Fuel Injectors	System operating normally	
Fuel Pump	System operating normally	
Fuel Filter	Good Condition	
Fuel Lines	System is sound with no apparent lea	aks
Fuel Tank	System is sound with no apparent lea	aks
Electrical System		
Dash Lights	All Bulbs and switches working prope	erly
Turn Signals	All Bulbs and switches working prope	erly
Dimmer Switch	All Bulbs and switches working prope	erly
Brake Lights	All Bulbs and switches working prope	erly
Tail Lights	All Bulbs and switches working prope	erly
Head Lights	All Bulbs and switches working prope	erly
Keyless Entry	Not applicable to this vehicle	
Cruise Control	System operating normally	
DVD Entertainment	Not applicable to this vehicle	
Backup Sensors	Not applicable to this vehicle	
Backup Camera	Not applicable to this vehicle	
GPS/Navigation	Not applicable to this vehicle	
Power Mirrors	System operating normally	
Power Liftgate	Not applicable to this vehicle	
Power Sliding Door(s)	Not applicable to this vehicle	
Power Sunroof	Not applicable to this vehicle	
Power Trunk	Not applicable to this vehicle	
Power Seat(s)	Not applicable to this vehicle	
Power Locks	Not applicable to this vehicle	
Power Windows	Not applicable to this vehicle	
Horn	System operating normally	
CD Player	System operating normally	
Radio	System operating normally	
Windshield Washers	System operating normally	
Windshield Wipers	System operating normally	
Dome Lights	All Bulbs and switches working prope	erly
License Plate Light	All Bulbs and switches working prope	erly
Backup Lights	All Bulbs and switches working prope	erly
Gauges / Indicators	System operating normally	
Miscellaneous		
Wiper Blades	Good Condition	21.98
Spare Tire & Jack	System operating normally	
Alignment	System operating normally	
Tire Pressure	Normal Condition	
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	
Rear Tires	Replaced Recently by Previous Own	er
Front Tires	Replaced Recently by Previous Own	er

*** OEM - Original Equipment from the Manufacturer