## Purchase this vehicle with complete confidence!

Vehicle Certified by Herman's Automotive 3350 N. Holland-Sylvania Rd

Toledo, OH 43615

**Extended Warrantys Available** 

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component Mechanics Evaluation Update Cost
Engine

Engine Management Sensors OEM – But still in very good condition Engine Mounts OEM – But still in very good condition

Ignition Coil Good Condition
Spark Plug Wires Good Condition
Spark Plugs Good Condition

 Vacuum Hoses
 OEM – But still in very good condition

 Air Filter
 Replaced by Herman's Automotive
 28.99

 Engine Oil & Filter
 Replaced by Herman's Automotive
 30.95

**Transmission** 

 4x4 Transfer Case
 Not applicable to this vehicle

 Linkage
 Not applicable to this vehicle

 Clutch
 Not applicable to this vehicle

 Differential
 Not applicable to this vehicle

 Shift Operation
 Shift is precise – No apparent slippage

 Fluid
 Fluid is clean and color is normal

**Brakes** 

ABS System System operating normally

Brake Lines Good Condition
Brake Hoses Good Condition

Wheel Speed Sensors System operating normally

Master Cylinder Good Condition
Wheel Hub Assembly Good Condition
Wheel Cylinders Good Condition
Brake Calipers Good Condition
Rear Rotors/Drums Good Condition

Front Rotors Replaced by Herman's Automotive 244.98

Rear Pads/Shoes 60-70% of Estimated pad life remaining

Front Pads Replaced by Herman's Automotive 69.99

Steering & Suspension

Power Steering Pump OEM – But still in very good condition
Power Steering Rack OEM – But still in very good condition
Springs OEM – But still in very good condition

Ball Joints Good Condition

CV Joints & Boots OEM – But still in very good condition
Universal Joints OEM – But still in very good condition

Universal Joints OEM – But still in very go
Outer Tie Rods Good Condition

Inner Tie Rods Good Condition

Rear Struts/Shocks OFM – But still in

Rear Struts/Shocks
OEM – But still in very good condition
Front Struts/Shocks
OEM – But still in very good condition
Steering Column
OEM – But still in very good condition
Control Arm Bushings
OEM – But still in very good condition
Stabilizer Bushings
OEM – But still in very good condition
Stabilizer Links
OEM – But still in very good condition

**Exhaust System** 

Tail Pipe OEM – But still in very good condition
Resonator OEM – But still in very good condition

Muffler Replaced by Herman's Automotive
Catalytic Converter OEM – But still in very good condition

Exhaust Pipe OEM – But still in very good condition

**Heating & Cooling System** 

Air Conditioning System operating normally

Heater Hoses OEM – But still in very good condition

Heater Performance System operating normally Blower Controls System operating normally

Fan OEM – But still in very good condition

Radiator Hoses/Cap Good Condition

Radiator OEM – But still in very good condition
Water Pump OEM – But still in very good condition
Belt Tensioner OEM – But still in very good condition

Belts Good Condition

Antifreeze Fluid is clean and color is norma

(888) 987-7788 sales@nicecarcompany.com

**NICE CAR COMPANY** 

\$1,493.82

**Completed Updates:** 

Muffler 1006.93 Wiper Blades 21.98 Tire Rotation & Wheel Balance 40.00 Front Rotors 244.98 Front Pads 69.99 Air Filter 28.99 30.95 **Engine Oil & Filter** Vehicle Inspection Fee 50

Component Mechanics Evaluation Update Cost

Starting / Charging System

Alternator / Regulator System operating normally Starter System operating normally

**Total Reconditioning Costs:** 

Battery Good Condition

**Fuel System** 

Fuel Injectors System operating normally Fuel Pump System operating normally

Fuel Filter Good Condition

Fuel Lines System is sound with no apparent leaks
Fuel Tank System is sound with no apparent leaks

**Electrical System** 

Turn Signals

All Bulbs and switches working properly
Dimmer Switch

All Bulbs and switches working properly
Brake Lights

All Bulbs and switches working properly
Tail Lights

All Bulbs and switches working properly
Head Lights

All Bulbs and switches working properly

Keyless Entry System operating normally Cruise Control System operating normally **DVD** Entertainment Not applicable to this vehicle **Backup Sensors** Not applicable to this vehicle Backup Camera Not applicable to this vehicle GPS/Navigation Not applicable to this vehicle System operating normally Power Mirrors Power Liftgate Not applicable to this vehicle Power Sliding Door(s) Not applicable to this vehicle Power Sunroof Not applicable to this vehicle

Power Trunk Switches and Motors Operating Normally
Power Seat(s) Switches and Motors Operating Normally
Power Locks Switches and Motors Operating Normally
Power Windows Switches and Motors Operating Normally

Horn System operating normally
CD Player System operating normally
Radio System operating normally
Windshield Washers System operating normally
Windshield Wipers System operating normally

Dash Lights All Bulbs and switches working properly
Dome Lights All Bulbs and switches working properly
License Plate Light All Bulbs and switches working properly
Backup Lights All Bulbs and switches working properly

Gauges / Indicators System operating normally

Miscellaneous

1006.93

Wiper Blades Replaced by Herman's Automotive
Spare Tire & Jack System operating normally

21.98

40.00

Alignment System operating normally
Tire Pressure Normal Condition

Tire Rotation & Wheel Balance Serviced by Herman's Automotive

Rear Tires 60-70% of Tread life remaining Front Tires 60-70% of Tread life remaining

\*\*\* OEM - Original Equipment from the Manufacturer