

## Purchase this vehicle with complete confidence!

**(888) 987-7788**  
sales@nicecarcompany.com

**NICE CAR COMPANY**

### Vehicle Certified by

Herman's Automotive  
3350 N. Holland-Sylvania Rd  
Toledo, OH 43615

### Extended Warrantys Available

12 Month / 15k Mile  
24 Month / 30k Mile  
36 Month / 36k Mile

| Component | Mechanics Evaluation | Update Cost |
|-----------|----------------------|-------------|
|-----------|----------------------|-------------|

#### Engine

|                           |                                        |       |
|---------------------------|----------------------------------------|-------|
| Engine Management Sensors | OEM – But still in very good condition |       |
| Engine Mounts             | OEM – But still in very good condition |       |
| Ignition Coil             | Good Condition                         |       |
| Spark Plug Wires          | Good Condition                         |       |
| Spark Plugs               | Good Condition                         |       |
| Vacuum Hoses              | OEM – But still in very good condition |       |
| Air Filter                | Replaced by Herman's Automotive        | 32.99 |
| Engine Oil & Filter       | Replaced by Herman's Automotive        | 30.95 |

#### Transmission

|                   |                                         |
|-------------------|-----------------------------------------|
| 4x4 Transfer Case | Not applicable to this vehicle          |
| Linkage           | Not applicable to this vehicle          |
| Clutch            | Not applicable to this vehicle          |
| Differential      | Not applicable to this vehicle          |
| Shift Operation   | Shift is precise – No apparent slippage |
| Fluid             | Fluid is clean and color is normal      |

#### Brakes

|                     |                                        |
|---------------------|----------------------------------------|
| ABS System          | System operating normally              |
| Brake Lines         | Good Condition                         |
| Brake Hoses         | Good Condition                         |
| Wheel Speed Sensors | System operating normally              |
| Master Cylinder     | Good Condition                         |
| Wheel Hub Assembly  | Good Condition                         |
| Wheel Cylinders     | Good Condition                         |
| Brake Calipers      | Good Condition                         |
| Rear Rotors/Drums   | Good Condition                         |
| Front Rotors        | Good Condition                         |
| Rear Pads/Shoes     | 70-80% of Estimated pad life remaining |
| Front Pads          | 70-80% of Estimated pad life remaining |

#### Steering & Suspension

|                      |                                        |
|----------------------|----------------------------------------|
| Power Steering Pump  | OEM – But still in very good condition |
| Power Steering Rack  | OEM – But still in very good condition |
| Springs              | OEM – But still in very good condition |
| Ball Joints          | Good Condition                         |
| CV Joints & Boots    | OEM – But still in very good condition |
| Universal Joints     | OEM – But still in very good condition |
| Outer Tie Rods       | Good Condition                         |
| Inner Tie Rods       | Good Condition                         |
| Rear Struts/Shocks   | OEM – But still in very good condition |
| Front Struts/Shocks  | OEM – But still in very good condition |
| Steering Column      | OEM – But still in very good condition |
| Control Arm Bushings | OEM – But still in very good condition |
| Stabilizer Bushings  | OEM – But still in very good condition |
| Stabilizer Links     | OEM – But still in very good condition |

#### Exhaust System

|                     |                                        |
|---------------------|----------------------------------------|
| Tail Pipe           | OEM – But still in very good condition |
| Resonator           | OEM – But still in very good condition |
| Muffler             | OEM – But still in very good condition |
| Catalytic Converter | OEM – But still in very good condition |
| Exhaust Pipe        | OEM – But still in very good condition |

#### Heating & Cooling System

|                    |                                        |
|--------------------|----------------------------------------|
| Air Conditioning   | System operating normally              |
| Heater Hoses       | OEM – But still in very good condition |
| Heater Performance | System operating normally              |
| Blower Controls    | System operating normally              |
| Fan                | OEM – But still in very good condition |
| Radiator Hoses/Cap | Good Condition                         |
| Radiator           | OEM – But still in very good condition |
| Water Pump         | OEM – But still in very good condition |
| Belt Tensioner     | OEM – But still in very good condition |
| Belts              | Good Condition                         |
| Antifreeze         | Fluid is clean and color is normal     |

### Completed Updates:

|                               |       |
|-------------------------------|-------|
| Tire Rotation & Wheel Balance | 40.00 |
| Air Filter                    | 32.99 |
| Engine Oil & Filter           | 30.95 |
| Vehicle Inspection Fee        | 50    |

**Total Reconditioning Costs: \$153.94**

| Component | Mechanics Evaluation | Update Cost |
|-----------|----------------------|-------------|
|-----------|----------------------|-------------|

#### Starting / Charging System

|                        |                           |
|------------------------|---------------------------|
| Alternator / Regulator | System operating normally |
| Starter                | System operating normally |
| Battery                | Good Condition            |

#### Fuel System

|                |                                        |
|----------------|----------------------------------------|
| Fuel Injectors | System operating normally              |
| Fuel Pump      | System operating normally              |
| Fuel Filter    | Good Condition                         |
| Fuel Lines     | System is sound with no apparent leaks |
| Fuel Tank      | System is sound with no apparent leaks |

#### Electrical System

|                       |                                         |
|-----------------------|-----------------------------------------|
| License Plate Light   | All Bulbs and switches working properly |
| Dome Lights           | All Bulbs and switches working properly |
| Dash Lights           | All Bulbs and switches working properly |
| Turn Signals          | All Bulbs and switches working properly |
| Dimmer Switch         | All Bulbs and switches working properly |
| Brake Lights          | All Bulbs and switches working properly |
| Tail Lights           | All Bulbs and switches working properly |
| Head Lights           | All Bulbs and switches working properly |
| Keyless Entry         | System operating normally               |
| Cruise Control        | System operating normally               |
| DVD Entertainment     | Not applicable to this vehicle          |
| Backup Sensors        | Not applicable to this vehicle          |
| Backup Camera         | System operating normally               |
| GPS/Navigation        | Not applicable to this vehicle          |
| Power Mirrors         | System operating normally               |
| Power Liftgate        | Not applicable to this vehicle          |
| Power Sliding Door(s) | Not applicable to this vehicle          |
| Power Sunroof         | Not applicable to this vehicle          |
| Power Trunk           | Switches and Motors Operating Normally  |
| Power Seat(s)         | Switches and Motors Operating Normally  |
| Power Locks           | Switches and Motors Operating Normally  |
| Power Windows         | Switches and Motors Operating Normally  |
| Horn                  | System operating normally               |
| CD Player             | System operating normally               |
| Radio                 | System operating normally               |
| Windshield Washers    | System operating normally               |
| Windshield Wipers     | System operating normally               |
| Backup Lights         | All Bulbs and switches working properly |
| Gauges / Indicators   | System operating normally               |

#### Miscellaneous

|                               |                                 |       |
|-------------------------------|---------------------------------|-------|
| Wiper Blades                  | Good Condition                  |       |
| Spare Tire & Jack             | System operating normally       |       |
| Alignment                     | System operating normally       |       |
| Tire Pressure                 | Normal Condition                |       |
| Tire Rotation & Wheel Balance | Serviced by Herman's Automotive | 40.00 |
| Rear Tires                    | 70-80% of Tread life remaining  |       |
| Front Tires                   | 70-80% of Tread life remaining  |       |

**\*\*\* OEM - Original Equipment from the Manufacturer**