Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component Mechanics Evaluation Update Cost

_			
-	nn	ın	_

Engine Management Sensors OEM – But still in very good condition
Engine Mounts OEM – But still in very good condition

Ignition Coil Good Condition
Spark Plugs Good Condition
Spark Plugs Good Condition

Spark Plugs Good Condition

Vacuum Hoses OEM – But still in very good condition

Air Filter Replaced by Herman's Automotive 28.99
Engine Oil & Filter Replaced by Herman's Automotive 59.95

Transmission

 4x4 Transfer Case
 Not applicable to this vehicle

 Linkage
 Not applicable to this vehicle

 Clutch
 Not applicable to this vehicle

 Differential
 Not applicable to this vehicle

 Shift Operation
 Shift is precise – No apparent slippage

 Fluid
 Fluid is clean and color is normal

Brakes

ABS System System operating normally

Brake Lines Good Condition
Brake Hoses Good Condition

Wheel Speed Sensors

Master Cylinder

Wheel Hub Assembly

Wheel Cylinders

Brake Calipers

Rear Rotors/Drums

Good Condition

Front Rotors

Good Condition

Rear Pads/Shoes 70-80% of Estimated pad life remaining Front Pads 70-80% of Estimated pad life remaining

Steering & Suspension

Power Steering Pump OEM – But still in very good condition
Power Steering Rack OEM – But still in very good condition
Springs OEM – But still in very good condition

Ball Joints Good Condition

CV Joints & Boots OEM – But still in very good condition
Universal Joints OEM – But still in very good condition

Outer Tie Rods Good Condition

Inner Tie Rods Good Condition

Rear Struts/Shocks OEM – But still in very good condition

Front Struts/Shocks OEM – But still in very good condition

Steering Column
Control Arm Bushings
Stabilizer Bushings
OEM – But still in very good condition
OEM – But still in very good condition
OEM – But still in very good condition
Stabilizer Bushings
OEM – But still in very good condition
OEM – But still in very good condition

Exhaust System

Tail Pipe OEM – But still in very good condition
Resonator OEM – But still in very good condition
Muffler OEM – But still in very good condition
Catalytic Converter OEM – But still in very good condition
Exhaust Pipe OEM – But still in very good condition

Heating & Cooling System

Air Conditioning System operating normally
Heater Hoses OEM – But still in very good

Heater Hoses OEM – But still in very good condition
Heater Performance System operating normally
Blower Controls System operating normally

Fan OEM – But still in very good condition

Radiator Hoses/Cap Good Condition

Radiator OEM – But still in very good condition
Water Pump OEM – But still in very good condition
Belt Tensioner OEM – But still in very good condition

Belts Good Condition

Antifreeze Fluid is clean and color is normal

(888) 987-7788

sales@nicecarcompany.com

NICE CAR COMPANY

Completed Updates:

Tire Rotation & Wheel Balance 40.00
Air Filter 28.99
Engine Oil & Filter 59.95
Vehicle Inspection Fee 50

Total Reconditioning Costs: \$178.94

Component Mechanics Evaluation Update Cost

Starting / Charging System

Alternator / Regulator System operating normally
Starter System operating normally
Battery Good Condition

Fuel System

Fuel Injectors

System operating normally

Fuel Pump

System operating normally

Fuel Lines Good Condition

Fuel Lines System is sound

Fuel Lines System is sound with no apparent leaks
Fuel Tank System is sound with no apparent leaks

Electrical System

License Plate Light All Bulbs and switches working properly Dome Lights All Bulbs and switches working properly Dash Lights All Bulbs and switches working properly All Bulbs and switches working properly Turn Signals All Bulbs and switches working properly Dimmer Switch **Brake Lights** All Bulbs and switches working properly Tail Lights All Bulbs and switches working properly All Bulbs and switches working properly Head Lights

Kevless Entry System operating normally Cruise Control System operating normally **DVD** Entertainment Not applicable to this vehicle Not applicable to this vehicle Backup Sensors Backup Camera Not applicable to this vehicle GPS/Navigation Not applicable to this vehicle Power Mirrors System operating normally Power Liftgate System operating normally

Power Sunroof Switches and Motors Operating Normally

Not applicable to this vehicle

Power Trunk Not applicable to this vehicle

Power Seat(s) Switches and Motors Operating Normally
Power Locks Switches and Motors Operating Normally
Power Windows Switches and Motors Operating Normally

Horn System operating normally
CD Player Not applicable to this vehicle
Radio System operating normally
Windshield Washers System operating normally
Windshield Wipers System operating normally

Backup Lights All Bulbs and switches working properly

Gauges / Indicators System operating normally

Miscellaneous

Power Sliding Door(s)

Wiper Blades Good Condition
Spare Tire & Jack System operating normally
Alignment System operating normally

Tire Pressure Normal Condition

Tire Rotation & Wheel Balance Serviced by Herman's Automotive

Rear Tires 70-80% of Tread life remaining Front Tires 70-80% of Tread life remaining

*** OEM - Original Equipment from the Manufacturer

40.00