Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation	Update Cost
Engine		
Engine Oil & Filter	Replaced by Herman's Automotive	30.95
Air Filter	Good Condition	
Vacuum Hoses	OEM - But still in very good condition	on
Spark Plugs	Good Condition	
Spark Plug Wires	Good Condition	
Ignition Coil	Good Condition	
Engine Mounts	OEM - But still in very good condition	on
Engine Management Sensors	OEM - But still in very good condition	on
Transmission		
Fluid	Fluid is clean and color is normal	

Differential	
Clutch	
Linkage	

Shift Operation Shift is precise - No apparent slippage Not applicable to this vehicle Not applicable to this vehicle Not applicable to this vehicle 4x4 Transfer Case Not applicable to this vehicle

Brakes Front Pads

70-80% of Estimated pad life remaining Rear Pads/Shoes 70-80% of Estimated pad life remaining Good Condition Front Rotors Rear Rotors/Drums **Good Condition Brake Calipers Good Condition** Wheel Cylinders Good Condition Wheel Hub Assembly Good Condition Master Cylinder **Good Condition**

Wheel Speed Sensors System operating normally

Brake Hoses Good Condition **Brake Lines** Good Condition ABS System System operating normally

Steering & Suspension

Stabilizer Links

OEM - But still in very good condition Stabilizer Bushings OEM - But still in very good condition Control Arm Bushings OEM - But still in very good condition Steering Column OEM – But still in very good condition Front Struts/Shocks OEM - But still in very good condition Rear Struts/Shocks OEM - But still in very good condition Inner Tie Rods **Good Condition** Outer Tie Rods **Good Condition** Universal Joints OEM - But still in very good condition CV Joints & Boots OEM - But still in very good condition **Ball Joints Good Condition** Springs OEM - But still in very good condition Power Steering Rack OEM - But still in very good condition Power Steering Pump OEM - But still in very good condition **Exhaust System**

Exhaust Pipe OEM - But still in very good condition Catalytic Converter OEM - But still in very good condition Muffler OEM - But still in very good condition Resonator OEM - But still in very good condition Tail Pipe OEM - But still in very good condition

Heating & Cooling System

Antifreeze Fluid is clean and color is normal Belts Good Condition Belt Tensioner OEM - But still in very good condition Water Pump OEM - But still in very good condition Radiator OEM - But still in very good condition Radiator Hoses/Cap Good Condition

OEM - But still in very good condition

Blower Controls System operating normally Heater Performance System operating normally

Heater Hoses OEM - But still in very good condition

Air Conditioning System operating normally

(888) 987-7788 sales@nicecarcompany.com

NICE CAR COMPANY

Completed Updates:

Engine Oil & Filter 30.95 Tire Rotation & Wheel Balance 40.00 Wiper Blades 21.98 Vehicle Inspection Fee 50 **Total Reconditioning Costs:** \$142.93

Component	Mechanics Evaluation	Update Cost

Component	Mechanics Evaluation Updat	e Cost
Starting / Charging System		
Battery	Good Condition	
Starter	System operating normally	
Alternator / Regulator	System operating normally	
Fuel System		
Fuel Tank	System is sound with no apparent leaks	
Fuel Lines	System is sound with no apparent leaks	
Fuel Filter	Good Condition	
Fuel Pump	System operating normally	
Fuel Injectors	System operating normally	
Electrical System		
Windshield Wipers	System operating normally	
Windshield Washers	System operating normally	
Radio	System operating normally	
CD Player	System operating normally	
Horn	System operating normally	
Power Windows	Switches and Motors Operating Normally	
Power Locks	Switches and Motors Operating Normally	
Power Seat(s)	Switches and Motors Operating Normally	
Power Trunk	Switches and Motors Operating Normally	
Power Sunroof	Not applicable to this vehicle	
Power Sliding Door(s)	Not applicable to this vehicle	
Power Liftgate	Not applicable to this vehicle	
Power Mirrors	System operating normally	
GPS/Navigation	Not applicable to this vehicle	
Backup Camera	Not applicable to this vehicle	
Backup Sensors	Not applicable to this vehicle	
DVD Entertainment	Not applicable to this vehicle	
Cruise Control	System operating normally	
Keyless Entry	System operating normally	
Head Lights	All Bulbs and switches working properly	
Tail Lights	All Bulbs and switches working properly	
Brake Lights	All Bulbs and switches working properly	
Dimmer Switch	All Bulbs and switches working properly	
Turn Signals	All Bulbs and switches working properly	
Dash Lights	All Bulbs and switches working properly	
Dome Lights	All Bulbs and switches working properly	
License Plate Light	All Bulbs and switches working properly	
Backup Lights	All Bulbs and switches working properly	
Gauges / Indicators	System operating normally	
Miscellaneous		
Front Tires	70-80% of Tread life remaining	
Rear Tires	70-80% of Tread life remaining	
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	40.00
Tire Pressure	Normal Condition	
Alianment	System energting normally	

*** OEM - Original Equipment from the Manufacturer

System operating normally

System operating normally

Replaced by Herman's Automotive

21.98

Alignment

Wiper Blades

Spare Tire & Jack