Purchase this vehicle with complete confidence!

Vehicle Certified by Herman's Automotive 3350 N. Holland-Sylvania F Toledo, OH 43615	۲d
Component	Mechanics

Extended Warrantys Available 12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation Up	odate Cost
Engine		
Engine Management Sensors	OEM - But still in very good condition	
Engine Mounts	OEM - But still in very good condition	
Ignition Coil	Good Condition	
Spark Plug Wires	Good Condition	
Spark Plugs	Good Condition	
Vacuum Hoses	OEM – But still in very good condition	
Air Filter	Good Condition	
Engine Oil & Filter	Replaced by Herman's Automotive	30.95
Transmission		
4x4 Transfer Case	Not applicable to this vehicle	
Linkage	Not applicable to this vehicle	
Clutch	Not applicable to this vehicle	
Differential	Not applicable to this vehicle	
Shift Operation	Shift is precise - No apparent slippag	e
Fluid	Fluid is clean and color is normal	
Brakes		
ABS System	System operating normally	
Brake Lines	Good Condition	
Brake Hoses	Good Condition	
Wheel Speed Sensors	System operating normally	
Master Cylinder	Good Condition	
Wheel Hub Assembly	Good Condition	
Wheel Cylinders	Good Condition	
Brake Calipers	Good Condition	
Rear Rotors/Drums	Good Condition	
Front Rotors	Replaced by Herman's Automotive	246.98
Rear Pads/Shoes	70-80% of Estimated pad life remaining	ng
Front Pads	Replaced by Herman's Automotive	69.99
Steering & Suspension		
Power Steering Pump	OEM – But still in very good condition	
Power Steering Rack	OEM - But still in very good condition	
Springs	OEM – But still in very good condition	
Ball Joints	Good Condition	
CV Joints & Boots	OEM – But still in very good condition	
Universal Joints	OEM – But still in very good condition	
Outer Tie Rods	Good Condition	
Inner Tie Rods	Good Condition	
Rear Struts/Shocks	OEM – But still in very good condition	
Front Struts/Shocks	OEM – But still in very good condition	
Steering Column	OEM – But still in very good condition	
Control Arm Bushings	OEM – But still in very good condition	
Stabilizer Bushings	OEM – But still in very good condition	
Stabilizer Links	OEM – But still in very good condition	
Exhaust System		
Tail Pipe	OEM - But still in very good condition	
Resonator	OEM – But still in very good condition	

Tail Pipe	OEM – But still in very good condition
Resonator	OEM – But still in very good condition
Muffler	OEM – But still in very good condition
Catalytic Converter	OEM – But still in very good condition
Exhaust Pipe	OEM – But still in very good condition

Heating & Cooling System

J	
Air Conditioning	System operating normally
Heater Hoses	OEM – But still in very good condition
Heater Performance	System operating normally
Blower Controls	System operating normally
Fan	OEM – But still in very good condition
Radiator Hoses/Cap	Good Condition
Radiator	OEM – But still in very good condition
Water Pump	OEM – But still in very good condition
Belt Tensioner	OEM – But still in very good condition
Belts	Good Condition
Antifreeze	Fluid is clean and color is normal



sales@nicecarcompany.com

Completed Updates:		
Tire Rotation & Wheel Balance	40.00	
Front Rotors	246.98	
Front Pads	69.99	
Engine Oil & Filter	30.95	
Vehicle Inspection Fee	50	
Total Reconditioning Costs:	\$437.92	

		_
Component	Mechanics Evaluation Upda	te Cost
Starting / Charging System		
Alternator / Regulator	System operating normally	
Starter	System operating normally	
Battery	Good Condition	
Fuel System		
Fuel Injectors	System operating normally	
Fuel Pump	System operating normally	
Fuel Filter	Good Condition	
Fuel Lines	System is sound with no apparent leaks	
Fuel Tank	System is sound with no apparent leaks	
Electrical System		
License Plate Light	All Bulbs and switches working properly	
Dome Lights	All Bulbs and switches working properly	
Dash Lights	All Bulbs and switches working properly	
Turn Signals	All Bulbs and switches working properly	
Dimmer Switch	All Bulbs and switches working properly	
Brake Lights	All Bulbs and switches working properly	
Tail Lights	All Bulbs and switches working properly	
Head Lights	All Bulbs and switches working properly	
Keyless Entry	System operating normally	
Cruise Control	System operating normally	
DVD Entertainment	Not applicable to this vehicle	
Backup Sensors	Not applicable to this vehicle	
Backup Camera	System operating normally	
GPS/Navigation	System operating normally	
Power Mirrors	System operating normally	
Power Liftgate	Not applicable to this vehicle	
Power Sliding Door(s)	Not applicable to this vehicle	
Power Sunroof	Switches and Motors Operating Normally	
Power Trunk	Switches and Motors Operating Normally	
Power Seat(s)	Switches and Motors Operating Normally	
Power Locks	Switches and Motors Operating Normally	
Power Windows	Switches and Motors Operating Normally	
Horn	System operating normally	
CD Player	System operating normally	
Radio	System operating normally	
Windshield Washers	System operating normally	
Windshield Wipers	System operating normally	
Backup Lights	All Bulbs and switches working properly	
Gauges / Indicators	System operating normally	
Miscellaneous		
Wiper Blades	Good Condition	
Spare Tire & Jack	System operating normally	
Alignment	System operating normally	
Tire Pressure	Normal Condition	
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	40.00
Rear Tires	70-80% of Tread life remaining	
Ensut Times		

*** OEM - Original Equipment from the Manufacturer

70-80% of Tread life remaining

Front Tires

NICE CAR COMPANY