Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation	Update Cost

Engine
Engine Management Sensors OEM – But still in very good condition
Engine Mounts OEM – But still in very good condition

Ignition Coil Good Condition
Spark Plug Wires Good Condition
Spark Plugs Good Condition

 Vacuum Hoses
 OEM – But still in very good condition

 Air Filter
 Replaced by Herman's Automotive
 26.99

 Engine Oil & Filter
 Replaced by Herman's Automotive
 30.95

Transmission

 4x4 Transfer Case
 Not applicable to this vehicle

 Linkage
 Not applicable to this vehicle

 Clutch
 Not applicable to this vehicle

 Differential
 Not applicable to this vehicle

 Shift Operation
 Shift is precise – No apparent slippage

 Fluid
 Fluid is clean and color is normal

Brakes

ABS System System operating normally

Brake Lines Good Condition
Brake Hoses Good Condition

Wheel Speed Sensors

Master Cylinder

Wheel Hub Assembly

Wheel Cylinders

System operating normally

Good Condition

Good Condition

Good Condition

Wheel Cylinders Good Condition
Brake Calipers Good Condition
Rear Rotors/Drums Good Condition
Front Rotors Good Condition
Rear Pads/Shoes 70-80% of Estima

Rear Pads/Shoes 70-80% of Estimated pad life remaining Front Pads 70-80% of Estimated pad life remaining

Steering & Suspension

Power Steering Pump OEM – But still in very good condition
Power Steering Rack OEM – But still in very good condition
Springs OEM – But still in very good condition

Ball Joints Good Condition

CV Joints & Boots OEM – But still in very good condition
Universal Joints OEM – But still in very good condition

Outer Tie Rods Good Condition
Inner Tie Rods Good Condition

Rear Struts/Shocks

Front Struts/Shocks

OEM – But still in very good condition

Steering Column

Control Arm Bushings

OEM – But still in very good condition

Exhaust System

Tail Pipe OEM – But still in very good condition
Resonator OEM – But still in very good condition
Muffler OEM – But still in very good condition
Catalytic Converter OEM – But still in very good condition
Exhaust Pipe OEM – But still in very good condition

Heating & Cooling System

Air Conditioning System operating normally

Heater Hoses OEM – But still in very good condition

Heater Performance System operating normally
Blower Controls System operating normally

Fan OEM – But still in very good condition

Radiator Hoses/Cap Good Condition

Radiator

OEM – But still in very good condition

Water Pump

OEM – But still in very good condition

Belt Tensioner

OEM – But still in very good condition

Belts Good Condition

Antifreeze Fluid is clean and color is normal

(888) 987-7788

sales@nicecarcompany.com

NICE CAR COMPANY

Completed Updates:

Tire Rotation & Wheel Balance 40.00
Air Filter 26.99
Engine Oil & Filter 30.95
Vehicle Inspection Fee 50

Total Reconditioning Costs: \$147.94

Component Mechanics Evaluation Update Cost

Starting / Charging System

Alternator / Regulator System operating normally Starter System operating normally

Battery Good Condition

Fuel System

Fuel Injectors System operating normally Fuel Pump System operating normally

Fuel Filter Good Condition

Fuel Lines System is sound with no apparent leaks
Fuel Tank System is sound with no apparent leaks

Electrical System

Gauges / Indicators System operating normally Backup Lights All Bulbs and switches working properly License Plate Light All Bulbs and switches working properly Dome Lights All Bulbs and switches working properly All Bulbs and switches working properly Dash Lights Turn Signals All Bulbs and switches working properly Dimmer Switch All Bulbs and switches working properly All Bulbs and switches working properly **Brake Lights** All Bulbs and switches working properly Tail Lights

Head Lights All Bulbs and switches working properly
Keyless Entry Not applicable to this vehicle
Cruise Control System operating normally
DVD Entertainment Not applicable to this vehicle

Backup Sensors
System operating normally
Backup Camera
System operating normally
GPS/Navigation
Not applicable to this vehicle
Power Mirrors
System operating normally
Power Liftgate
Not applicable to this vehicle
Power Sliding Door(s)
Not applicable to this vehicle

Power Sunroof Switches and Motors Operating Normally
Power Trunk Switches and Motors Operating Normally
Power Seat(s) Switches and Motors Operating Normally
Power Locks Switches and Motors Operating Normally

Switches and Motors Operating Normally

40.00

Horn System operating normally CD Player System operating normally Radio System operating normally Windshield Washers System operating normally Windshield Wipers System operating normally

Miscellaneous

Power Windows

Wiper Blades Good Condition

Spare Tire & Jack System operating normally Alignment System operating normally

Tire Pressure Normal Condition

Tire Rotation & Wheel Balance Serviced by Herman's Automotive

Rear Tires 70-80% of Tread life remaining Front Tires 70-80% of Tread life remaining

*** OEM - Original Equipment from the Manufacturer