# Purchase this vehicle with complete confidence!

## Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

### **Extended Warrantys Available**

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation	Update Cost
Engine	·	·

Engine	
Engine Oil & Filter	Replaced by Herman's Automotive
Air Filter	Good Condition
Vacuum Hoses	OEM – But still in very good condition

Spark Plugs Good Condition
Spark Plug Wires Good Condition
Ignition Coil Good Condition

Engine Mounts OEM – But still in very good condition
Engine Management Sensors OEM – But still in very good condition

#### Transmission

Fluid Fluid is clean and color is normal
Shift Operation Shift is precise – No apparent slippage
Differential Not applicable to this vehicle
Clutch Not applicable to this vehicle
Linkage Not applicable to this vehicle
4x4 Transfer Case Not applicable to this vehicle

#### **Brakes**

Front Pads 70-80% of Estimated pad life remaining Rear Pads/Shoes 70-80% of Estimated pad life remaining

Front Rotors
Front Rotors/Drums
Good Condition
Good Condition
Brake Calipers
Good Condition
Wheel Cylinders
Good Condition
Wheel Hub Assembly
Good Condition
Master Cylinder
Good Condition

Wheel Speed Sensors System operating normally

Brake Hoses Good Condition
Brake Lines Good Condition

ABS System System operating normally

#### Steering & Suspension

 Stabilizer Links
 OEM – But still in very good condition

 Stabilizer Bushings
 OEM – But still in very good condition

 Control Arm Bushings
 OEM – But still in very good condition

 Steering Column
 OEM – But still in very good condition

 Front Struts/Shocks
 OEM – But still in very good condition

 Rear Struts/Shocks
 OEM – But still in very good condition

 Inner Tie Rods
 Good Condition

Outer Tie Rods Good Condition
Universal Joints OEM – But still in very good condition
CV Joints & Boots OEM – But still in very good condition
Ball Joints Good Condition

Springs OEM – But still in very good condition

Power Steering Rack OEM – But still in very good condition

Power Steering Pump OEM – But still in very good condition

# **Exhaust System**

Exhaust Pipe OEM – But still in very good condition
Catalytic Converter OEM – But still in very good condition
Muffler OEM – But still in very good condition
Resonator OEM – But still in very good condition
Tail Pipe OEM – But still in very good condition

#### **Heating & Cooling System**

Antifreeze Fluid is clean and color is normal
Belts Good Condition
Belt Tensioner OEM – But still in very good condition

Water Pump
OEM – But still in very good condition
Radiator
OEM – But still in very good condition
Robert Pump
OEM – But still in very good condition

Radiator Hoses/Cap Good Condition

Fan OEM – But still in very good condition Blower Controls System operating normally

Blower Controls System operating normally
Heater Performance System operating normally

Heater Hoses OEM – But still in very good condition

Air Conditioning System operating normally

# (888) 987-7788

sales@nicecarcompany.com

# **NICE CAR COMPANY**

# **Completed Updates:**

Vehicle Inspection Fee 50

Total Reconditioning Costs: \$50.00

Component	Mechanics Evaluation	Update Cost
Starting / Charging System		
Battery	Good Condition	
Starter	System operating normally	
Alternator / Regulator	System operating normally	
Fuel System		
Fuel Tank	System is sound with no apparent	leaks
Fuel Lines	System is sound with no apparent leaks	
Fuel Filter	Good Condition	
Fuel Pump	System operating normally	
Fuel Injectors	System operating normally	
Electrical System		
Windshield Wipers	System operating normally	
Windshield Washers	System operating normally	
Radio	System operating normally	
CD Player	System operating normally	
Horn	System operating normally	
Power Windows	Switches and Motors Operating Normally	
Power Locks	Switches and Motors Operating Normally	
Power Seat(s)	Switches and Motors Operating Normally	
Power Trunk	Switches and Motors Operating Normally	
Power Sunroof	Not applicable to this vehicle	
Power Sliding Door(s)	Not applicable to this vehicle	
Power Liftgate	Not applicable to this vehicle	
Power Mirrors	System operating normally	
GPS/Navigation	Not applicable to this vehicle	
Backup Camera	System operating normally	
Backup Sensors	Not applicable to this vehicle	
DVD Entertainment	Not applicable to this vehicle	
Cruise Control	System operating normally	
Keyless Entry	System operating normally	
Head Lights	All Bulbs and switches working pr	operly
Tail Lights	All Bulbs and switches working pr	operly
Brake Lights	All Bulbs and switches working pr	operly
Dimmer Switch	All Bulbs and switches working pr	
Turn Signals	All Bulbs and switches working pro	
ash Lights All Bulbs and switches working properly		operly
Dome Lights	All Bulbs and switches working pr	operly
License Plate Light	All Bulbs and switches working pr	operly
B. 1. 12.14	AUD II	

# Gauges / Indicators Miscellaneous

Backup Lights

Front Tires 70-80% of Tread life remaining
Rear Tires 70-80% of Tread life remaining
Tire Rotation & Wheel Balance Serviced by Herman's Automotive

Tire Pressure Normal Condition

Alignment System operating normally Spare Tire & Jack System operating normally

Winer Blades Good Condition

## \*\*\* OEM - Original Equipment from the Manufacturer

All Bulbs and switches working properly

System operating normally