## Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

## **Extended Warrantys Available**

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation	Update Cost

Engine	
Engine Management Sensors	OEM – But still in very good condition
Engine Mounts	OEM – But still in very good condition

Ignition Coil Good Condition
Spark Plug Wires Good Condition
Spark Plugs Good Condition

 Vacuum Hoses
 OEM – But still in very good condition

 Air Filter
 Replaced by Herman's Automotive
 31.99

 Engine Oil & Filter
 Replaced by Herman's Automotive
 46.46

Transmission

 4x4 Transfer Case
 Not applicable to this vehicle

 Linkage
 Not applicable to this vehicle

 Clutch
 Not applicable to this vehicle

 Differential
 Not applicable to this vehicle

 Shift Operation
 Shift is precise – No apparent slippage

 Fluid
 Fluid is clean and color is normal

**Brakes** 

ABS System System operating normally

Brake Lines Good Condition
Brake Hoses Good Condition

Wheel Speed Sensors

Master Cylinder

Wheel Hub Assembly

Wheel Cylinders

Brake Calipers

Rear Rotors/Drums

System operating normally

Good Condition

Good Condition

Good Condition

Good Condition

Rear Pads/Shoes 70-80% of Estimated pad life remaining Front Pads 70-80% of Estimated pad life remaining

Good Condition

Steering & Suspension

Front Rotors

Power Steering Pump
OEM – But still in very good condition
Power Steering Rack
OEM – But still in very good condition
Springs
OEM – But still in very good condition

Ball Joints Good Condition

CV Joints & Boots

OEM – But still in very good condition
Universal Joints

OEM – But still in very good condition

Outer Tie Rods **Good Condition** Inner Tie Rods Good Condition Rear Struts/Shocks OEM - But still in very good condition Front Struts/Shocks OEM - But still in very good condition OEM - But still in very good condition Steering Column Control Arm Bushings OEM - But still in very good condition Stabilizer Bushings OEM - But still in very good condition Stabilizer Links OEM - But still in very good condition

**Exhaust System** 

Tail Pipe OEM – But still in very good condition
Resonator OEM – But still in very good condition
Muffler OEM – But still in very good condition
Catalytic Converter OEM – But still in very good condition
Exhaust Pipe OEM – But still in very good condition

**Heating & Cooling System** 

Air Conditioning System operating normally
Heater Hoses OEM – But still in very good condition

Heater Performance System operating normally
Blower Controls System operating normally

Fan OEM – But still in very good condition

Radiator Hoses/Cap Good Condition

Radiator OEM – But still in very good condition
Water Pump OEM – But still in very good condition
Belt Tensioner OEM – But still in very good condition

Belts Good Condition

Antifreeze Fluid is clean and color is normal

## (888) 987-7788

sales@ńicecarcompany.com

**NICE CAR COMPANY** 

**Completed Updates:** 

Tire Rotation & Wheel Balance 40.00
Air Filter 31.99
Engine Oil & Filter 46.46
Vehicle Inspection Fee 50

Total Reconditioning Costs: \$168.45

Component Mechanics Evaluation Update Cost

Starting / Charging System

Alternator / Regulator System operating normally
Starter System operating normally
Battery Good Condition

Fuel System

Fuel Injectors System operating normally
Fuel Pump System operating normally
Fuel Filter Good Condition

Fuel Lines System is sound with no apparent leaks
Fuel Tank System is sound with no apparent leaks

**Electrical System** 

License Plate Light All Bulbs and switches working properly Dome Lights All Bulbs and switches working properly Dash Lights All Bulbs and switches working properly All Bulbs and switches working properly Turn Signals All Bulbs and switches working properly Dimmer Switch **Brake Lights** All Bulbs and switches working properly Tail Lights All Bulbs and switches working properly Head Lights All Bulbs and switches working properly

Kevless Entry Not applicable to this vehicle Cruise Control System operating normally **DVD** Entertainment Not applicable to this vehicle **Backup Sensors** Not applicable to this vehicle Backup Camera System operating normally GPS/Navigation Not applicable to this vehicle Power Mirrors System operating normally Power Liftgate Not applicable to this vehicle Power Sliding Door(s) Not applicable to this vehicle

Power Trunk Switches and Motors Operating Normally

Not applicable to this vehicle

Power Seat(s) Not applicable to this vehicle

Power Locks Switches and Motors Operating Normally
Power Windows Switches and Motors Operating Normally

Horn System operating normally
CD Player Not applicable to this vehicle
Radio System operating normally
Windshield Washers System operating normally
Windshield Wipers System operating normally

Backup Lights All Bulbs and switches working properly

Gauges / Indicators System operating normally

Miscellaneous

Power Sunroof

Wiper Blades Good Condition
Spare Tire & Jack System operating normally
Alignment System operating normally

Tire Pressure Normal Condition

Tire Rotation & Wheel Balance Serviced by Herman's Automotive

Rear Tires 70-80% of Tread life remaining Front Tires 70-80% of Tread life remaining

\*\*\* OEM - Original Equipment from the Manufacturer

40.00