Purchase this vehicle with complete confidence!

Vehi	cle	Ce	rtifie	d	by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available 12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation Upo	ate Cost	
Engine			
Engine Management Sensors	OEM – But still in very good condition		
Engine Mounts	OEM – But still in very good condition		
Ignition Coil	Good Condition		
Spark Plug Wires	Good Condition		
Spark Plugs	Good Condition		
Vacuum Hoses	OEM – But still in very good condition		
Air Filter	Replaced by Herman's Automotive	29.99	
Engine Oil & Filter	Replaced by Herman's Automotive	30.95	
Transmission			
4x4 Transfer Case	Not applicable to this vehicle		
Linkage	Not applicable to this vehicle		
Clutch	Not applicable to this vehicle		
Differential	Not applicable to this vehicle		
Shift Operation	Shift is precise - No apparent slippage		
Fluid	Fluid is clean and color is normal		
Brakes			
ABS System	System operating normally		
Brake Lines	Good Condition		
Brake Hoses	Good Condition		
Wheel Speed Sensors	System operating normally		
Master Cylinder	Good Condition		
Wheel Hub Assembly	Good Condition		
Wheel Cylinders	Good Condition		
Brake Calipers	Good Condition		
Rear Rotors/Drums	Good Condition		
Front Rotors	Good Condition	246.98	
Rear Pads/Shoes	60-70% of Estimated pad life remaining	1	
Front Pads	70-80% of Estimated pad life remaining		
Steering & Suspension			
Power Steering Pump	OEM – But still in very good condition		
Power Steering Rack	OEM – But still in very good condition		
Springs	OEM – But still in very good condition		
Ball Joints	Good Condition		
CV Joints & Boots	OEM – But still in very good condition		
Universal Joints	OEM – But still in very good condition		
Outer Tie Rods	Good Condition		
Inner Tie Rods	Good Condition		
Rear Struts/Shocks	OEM – But still in very good condition		
Front Struts/Shocks	OEM – But still in very good condition		
Steering Column	OEM – But still in very good condition		
Control Arm Bushings	OEM – But still in very good condition		
Stabilizer Bushings	OEM – But still in very good condition		
Stabilizer Links	OEM – But still in very good condition		
Exhaust System			
Tail Pipe	OEM – But still in very good condition		
Resonator	OEM – But still in very good condition		
Muffler	OEM – But still in very good condition		
Catalytic Converter	OEM – But still in very good condition		
Exhaust Dina			

OEM - But still in very good condition OEM - But still in very good condition

Heating & Cooling System

Exhaust Pipe

Air Conditioning System operating normally Heater Hoses OEM - But still in very good condition Heater Performance System operating normally Blower Controls System operating normally Fan OEM - But still in very good condition Radiator Hoses/Cap Good Condition Radiator OEM - But still in very good condition Water Pump OEM - But still in very good condition **Belt Tensioner** OEM - But still in very good condition Belts Good Condition Antifreeze Fluid is clean and color is normal



sales@nicecarcompany.com

Completed Updates:					
Tire Rotation & Wheel Balance	40.00				
Front Rotors	246.98				
Front Pads	69.99				
Air Filter	29.99				
Engine Oil & Filter	30.95				
Vehicle Inspection Fee	50				
Total Reconditioning Costs:	\$467.91				

NICE CAR COMPANY

Component	Mechanics Evaluation Upda	te Cost
Starting / Charging System		
Alternator / Regulator	System operating normally	
Starter	System operating normally	
Battery	Good Condition	
-		
Fuel System Fuel Injectors	System operating normally	
Fuel Pump	System operating normally	
Fuel Filter	Good Condition	
Fuel Lines	System is sound with no apparent leaks	
Fuel Tank	System is sound with no apparent leaks	
	System is sound with no apparent leaks	
Electrical System		
Dash Lights	All Bulbs and switches working properly	
Turn Signals	All Bulbs and switches working properly	
Dimmer Switch	All Bulbs and switches working properly	
Brake Lights	All Bulbs and switches working properly	
Tail Lights	All Bulbs and switches working properly	
Head Lights	All Bulbs and switches working properly	
Keyless Entry	System operating normally	
Cruise Control	System operating normally	
DVD Entertainment	Not applicable to this vehicle	
Backup Sensors	System operating normally	
Backup Camera	System operating normally	
GPS/Navigation	Not applicable to this vehicle	
Power Mirrors	System operating normally	
Power Liftgate	Not applicable to this vehicle	
Power Sliding Door(s)	Not applicable to this vehicle	
Power Sunroof	Not applicable to this vehicle	
Power Trunk	Switches and Motors Operating Normally	
Power Seat(s)	Switches and Motors Operating Normally	,
Power Locks	Switches and Motors Operating Normally	,
Power Windows	Switches and Motors Operating Normally	,
Horn	System operating normally	
CD Player	System operating normally	
Radio	System operating normally	
Windshield Washers	System operating normally	
Windshield Wipers	System operating normally	
Dome Lights	All Bulbs and switches working properly	
License Plate Light	All Bulbs and switches working properly	
Backup Lights	All Bulbs and switches working properly	
Gauges / Indicators	System operating normally	
Miscellaneous		
Wiper Blades	Good Condition	
Spare Tire & Jack	System operating normally	
Alignment	System operating normally	
Tire Pressure	Normal Condition	
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	40.00
Rear Tires	70-80% of Tread life remaining	
Front Tires	70-80% of Tread life remaining	

*** OEM - Original Equipment from the Manufacturer

ſ