## Purchase this vehicle with complete confidence!

Vehicle Certified by
Herman's Automotive

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

**Extended Warrantys Available** 

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component Mechanics Evaluation Update Cost

Engine

Engine Management Sensors OEM – But still in very good condition
Engine Mounts OEM – But still in very good condition

Ignition Coil Good Condition
Spark Plug Wires Good Condition
Spark Plugs Good Condition

Vacuum Hoses OEM – But still in very good condition

Air Filter Good Condition

Engine Oil & Filter Replaced by Herman's Automotive 46.46

**Transmission** 

 4x4 Transfer Case
 Not applicable to this vehicle

 Linkage
 Not applicable to this vehicle

 Clutch
 Not applicable to this vehicle

 Differential
 Not applicable to this vehicle

 Shift Operation
 Shift is precise – No apparent slippage

 Fluid
 Fluid is clean and color is normal

Brakes

ABS System System operating normally

Brake Lines Good Condition
Brake Hoses Good Condition

Wheel Speed Sensors System operating normally

Master Cylinder Good Condition
Wheel Hub Assembly Good Condition
Wheel Cylinders Good Condition
Brake Calipers Good Condition

 Rear Rotors/Drums
 Replaced by Herman's Automotive
 242.98

 Front Rotors
 Replaced by Herman's Automotive
 246.98

 Rear Pads/Shoes
 Replaced by Herman's Automotive
 69.99

 Front Pads
 Replaced by Herman's Automotive
 69.99

Steering & Suspension

Power Steering Pump OEM – But still in very good condition
Power Steering Rack OEM – But still in very good condition
Springs OEM – But still in very good condition

Ball Joints Good Condition

CV Joints & Boots OEM – But still in very good condition
Universal Joints OEM – But still in very good condition

Outer Tie Rods Good Condition
Inner Tie Rods Good Condition

Rear Struts/Shocks

Front Struts/Shocks

OEM – But still in very good condition

OEM – But still in very good condition

Steering Column

OEM – But still in very good condition

Control Arm Bushings

OEM – But still in very good condition

Stabilizer Bushings

OEM – But still in very good condition

Stabilizer Links

OEM – But still in very good condition

**Exhaust System** 

Tail Pipe OEM – But still in very good condition
Resonator OEM – But still in very good condition
Muffler OEM – But still in very good condition
Catalytic Converter OEM – But still in very good condition
Exhaust Pipe OEM – But still in very good condition

**Heating & Cooling System** 

Air Conditioning System operating normally

Heater Hoses OEM – But still in very good condition

Heater Performance System operating normally Blower Controls System operating normally

Fan OEM – But still in very good condition

Radiator Hoses/Cap Good Condition

Radiator OEM – But still in very good condition
Water Pump OEM – But still in very good condition
Belt Tensioner OEM – But still in very good condition

Belts Good Condition

Antifreeze Fluid is clean and color is normal

## (888) 987-7788

sales@nicecarcompany.com

**NICE CAR COMPANY** 

**Completed Updates:** 

Tire Rotation & Wheel Balance 40 00 Rear Rotors/Drums 242.98 Front Rotors 246.98 Rear Pads/Shoes 69.99 Front Pads 69.99 **Engine Oil & Filter** 46.46 Vehicle Inspection Fee 50 **Total Reconditioning Costs:** \$766.40

Component Mechanics Evaluation Update Cost

Starting / Charging System

Alternator / Regulator System operating normally Starter System operating normally

Battery Good Condition

Fuel System

Fuel Injectors System operating normally
Fuel Pump System operating normally

Fuel Filter Good Condition

Fuel Lines System is sound with no apparent leaks
Fuel Tank System is sound with no apparent leaks

**Electrical System** 

Turn Signals

All Bulbs and switches working properly
Dimmer Switch

All Bulbs and switches working properly
Brake Lights

All Bulbs and switches working properly
Tail Lights

All Bulbs and switches working properly
Head Lights

All Bulbs and switches working properly
All Bulbs and switches working properly

 Keyless Entry
 System operating normally

 Cruise Control
 System operating normally

 DVD Entertainment
 Not applicable to this vehicle

 Backup Sensors
 Not applicable to this vehicle

 Backup Camera
 System operating normally

 GPS/Navigation
 Not applicable to this vehicle

Power Mirrors

System operating normally

Power Liftgate

Not applicable to this vehicle

Power Sliding Door(s)

Not applicable to this vehicle

Power Sunroof

Not applicable to this vehicle

Power Trunk

Switches and Motors Operating Normally

Power Seat(s) Switches and Motors Operating Normally
Power Locks Switches and Motors Operating Normally
Power Windows Switches and Motors Operating Normally
Horn System operating normally

Horn System operating normally
CD Player Not applicable to this vehicle
Radio System operating normally
Windshield Washers System operating normally
Windshield Wipers System operating normally

Dash Lights All Bulbs and switches working properly
Dome Lights All Bulbs and switches working properly
License Plate Light All Bulbs and switches working properly
Backup Lights All Bulbs and switches working properly

Gauges / Indicators System operating normally

Miscellaneous

Wiper Blades Good Condition
Spare Tire & Jack System operating normally
Alignment System operating normally

Tire Pressure Normal Condition

Tire Rotation & Wheel Balance Serviced by Herman's Automotive Rear Tires 70-80% of Tread life remaining

Front Tires 70-80% of Tread life remaining

\*\*\* OEM - Original Equipment from the Manufacturer

40.00