Purchase this vehicle with complete confidence!

Vehicle Certified by Herman's Automotive

Toledo, OH 43615

3350 N. Holland-Sylvania Rd

Extended Warrantys Available

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component Mechanics Evaluation Update Cost

Engine

Engine Management Sensors OEM – But still in very good condition
Engine Mounts OEM – But still in very good condition

Ignition Coil Good Condition
Spark Plug Wires Good Condition

Spark Plug Wires Good Condition
Spark Plugs Good Condition

Vacuum Hoses OEM – But still in very good condition
Air Filter Replaced by Herman's Automotive 34.99
Engine Oil & Filter Replaced by Herman's Automotive 36.95

Transmission

 4x4 Transfer Case
 Not applicable to this vehicle

 Linkage
 Not applicable to this vehicle

 Clutch
 Not applicable to this vehicle

 Differential
 Not applicable to this vehicle

 Shift Operation
 Shift is precise – No apparent

Shift Operation Shift is precise – No apparent slippage Fluid Fluid is clean and color is normal

Brakes

ABS System System operating normally

Brake Lines Good Condition
Brake Hoses Good Condition

Wheel Speed Sensors System operating normally

 Master Cylinder
 Good Condition

 Wheel Hub Assembly
 Good Condition

 Wheel Cylinders
 Good Condition

 Brake Calipers
 Good Condition

 Rear Rotors/Drums
 Good Condition

 Front Rotors
 Good Condition

Rear Pads/Shoes 70-80% of Estimated pad life remaining Front Pads 70-80% of Estimated pad life remaining

Steering & Suspension

Power Steering Pump OEM – But still in very good condition
Power Steering Rack Replaced by Herman's Automotive 499.99

Springs OEM – But still in very good condition

Ball Joints Good Condition

CV Joints & Boots OEM – But still in very good condition
Universal Joints OEM – But still in very good condition

Outer Tie Rods Good Condition

Inner Tie Rods Replaced by Herman's Automotive 153.98

Rear Struts/Shocks
OEM – But still in very good condition
Front Struts/Shocks
OEM – But still in very good condition
Steering Column
OEM – But still in very good condition
Control Arm Bushings
OEM – But still in very good condition

Stabilizer Bushings OEM – But still in very good condition
Stabilizer Links Replaced by Herman's Automotive

Exhaust System

Tail Pipe OEM – But still in very good condition
Resonator OEM – But still in very good condition
Muffler OEM – But still in very good condition
Catalytic Converter OEM – But still in very good condition
Exhaust Pipe Replaced by Herman's Automotive 258.97

Heating & Cooling System

Air Conditioning System operating normally

Heater Hoses OEM – But still in very good condition

Heater Performance System operating normally Blower Controls System operating normally

Fan OEM – But still in very good condition

Radiator Hoses/Cap Good Condition

Radiator OEM – But still in very good condition
Water Pump OEM – But still in very good condition
Belt Tensioner OEM – But still in very good condition

Belts Good Condition

Antifreeze Fluid is clean and color is norma

(888) 987-7788 sales@nicecarcompany.com

NICE CAR COMPANY

Completed Updates:

 Exhaust Pipe
 258.97

 Power Steering Rack
 499.99

 Inner Tie Rods
 153.98

 Stabilizer Links
 411.48

 Air Filter
 34.99

 Engine Oil & Filter
 36.95

 Vehicle Inspection Fee
 50

Total Reconditioning Costs: \$1,446.36

Component Mechanics Evaluation Update Cost

Starting / Charging System

Alternator / Regulator System operating normally Starter System operating normally

Battery Good Condition

Fuel System

Fuel Injectors

System operating normally

Fuel Pump

System operating normally

Fuel Filter Good Condition

Fuel Lines System is sound with no apparent leaks
Fuel Tank System is sound with no apparent leaks

Electrical System

Turn Signals All Bulbs and switches working properly
Dimmer Switch All Bulbs and switches working properly
Brake Lights All Bulbs and switches working properly
Tail Lights All Bulbs and switches working properly

Head Lights All Bulbs and switches working properly
Keyless Entry System operating normally
Cruise Control System operating normally
DVD Entertainment Not applicable to this vehicle

Backup Sensors Not applicable to this vehicle Backup Camera System operating normally GPS/Navigation Not applicable to this vehicle Power Mirrors System operating normally Power Liftgate Not applicable to this vehicle Power Sliding Door(s) Not applicable to this vehicle Power Sunroof Not applicable to this vehicle Power Trunk Not applicable to this vehicle

Power Seat(s) Switches and Motors Operating Normally
Power Locks Switches and Motors Operating Normally
Power Windows Switches and Motors Operating Normally

Horn System operating normally
CD Player Not applicable to this vehicle
Radio System operating normally
Windshield Washers System operating normally
Windshield Wipers System operating normally

Dash Lights All Bulbs and switches working properly
Dome Lights All Bulbs and switches working properly
License Plate Light All Bulbs and switches working properly
Backup Lights All Bulbs and switches working properly

Gauges / Indicators System operating normally

Miscellaneous

411.48

Wiper Blades Good Condition
Spare Tire & Jack System operating normally
Alignment System operating normally

Tire Pressure Normal Condition

Tire Rotation & Wheel Balance Serviced by Herman's Automotive Rear Tires 70-80% of Tread life remaining Front Tires 70-80% of Tread life remaining

*** OEM - Original Equipment from the Manufacturer