Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation	Update Cost
Engine		

Engine	
Engine Oil & Filter	Replaced by Herman's Automotive
Air Filter	Good Condition
Vacuum Hoses	OEM – But still in very good condition
Spark Plugs	Good Condition
Spark Plug Wires	Good Condition

Good Condition

Engine Mounts OEM - But still in very good condition **Engine Management Sensors** OEM - But still in very good condition

Transmission

Ignition Coil

Fluid is clean and color is normal Fluid Shift Operation Shift is precise - No apparent slippage Differential Not applicable to this vehicle Clutch Not applicable to this vehicle Linkage Not applicable to this vehicle 4x4 Transfer Case Not applicable to this vehicle

Brakes

Front Pads 70-80% of Estimated pad life remaining Rear Pads/Shoes 70-80% of Estimated pad life remaining

Good Condition Front Rotors Rear Rotors/Drums **Good Condition Brake Calipers Good Condition** Wheel Cylinders Good Condition Wheel Hub Assembly Good Condition Master Cylinder **Good Condition**

Wheel Speed Sensors System operating normally

Brake Hoses Good Condition **Brake Lines** Good Condition ABS System System operating normally

Steering & Suspension

Stabilizer Links OEM - But still in very good condition Stabilizer Bushings OEM - But still in very good condition Control Arm Bushings OEM - But still in very good condition Steering Column OEM – But still in very good condition Front Struts/Shocks OEM - But still in very good condition Rear Struts/Shocks OEM - But still in very good condition Inner Tie Rods **Good Condition** Outer Tie Rods **Good Condition** Universal Joints OEM - But still in very good condition CV Joints & Boots OEM - But still in very good condition

Ball Joints Good Condition

Springs OEM - But still in very good condition Power Steering Rack OEM - But still in very good condition Power Steering Pump OEM - But still in very good condition

Exhaust System

Exhaust Pipe OEM - But still in very good condition Catalytic Converter OEM - But still in very good condition Muffler OEM - But still in very good condition Resonator OEM - But still in very good condition Tail Pipe OEM - But still in very good condition

Heating & Cooling System

Antifreeze Fluid is clean and color is normal Belts Good Condition Belt Tensioner OEM - But still in very good condition Water Pump OEM - But still in very good condition Radiator OEM - But still in very good condition

Radiator Hoses/Cap Good Condition

OEM - But still in very good condition

Blower Controls System operating normally Heater Performance System operating normally

Heater Hoses OEM - But still in very good condition

Air Conditioning System operating normally

(888) 987-7788

sales@nicecarcompany.com

NICE CAR COMPANY

Completed Updates:

Vehicle Inspection Fee 50 **Total Reconditioning Costs:** \$50.00

Component	Mechanics Evaluation	Update Cost
Starting / Charging System		
Battery	Good Condition	
Starter	System operating normally	
Alternator / Regulator	System operating normally	
Fuel System		
Fuel Tank	System is sound with no apparent	leaks
Fuel Lines	System is sound with no apparent	
Fuel Filter	Good Condition	
Fuel Pump	System operating normally	
Fuel Injectors	System operating normally	
Electrical System		
Windshield Wipers	System operating normally	
Windshield Washers	System operating normally	
Radio	System operating normally	
CD Player	System operating normally	
Horn	System operating normally	
Power Windows	Switches and Motors Operating N	ormally
Power Locks	Switches and Motors Operating N	ormally
Power Seat(s)	Switches and Motors Operating N	ormally
Power Trunk	Switches and Motors Operating N	ormally
Power Sunroof	Not applicable to this vehicle	
Power Sliding Door(s)	Not applicable to this vehicle	
Power Liftgate	Not applicable to this vehicle	
Power Mirrors	System operating normally	
GPS/Navigation	Not applicable to this vehicle	
Backup Camera	Not applicable to this vehicle	
Backup Sensors	Not applicable to this vehicle	
DVD Entertainment	Not applicable to this vehicle	
Cruise Control	System operating normally	
Keyless Entry	System operating normally	
Head Lights	All Bulbs and switches working pro	operly
Tail Lights	All Bulbs and switches working pro	operly
Brake Lights	All Bulbs and switches working pro	operly
Dimmer Switch	All Bulbs and switches working pro	operly
Turn Signals	All Bulbs and switches working pro	operly
Dash Lights	All Bulbs and switches working pro	operly
Dome Lights	All Bulbs and switches working pro	operly
License Plate Light	All Bulbs and switches working pro	operly
Backup Lights	All Bulbs and switches working pro	operly
Gauges / Indicators	System operating normally	
Miscellaneous		
Front Tires	70-80% of Tread life remaining	
Rear Tires	70-80% of Tread life remaining	
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	•
Tire Pressure	Normal Condition	
Alignment	System operating normally	
O Tine 0 II	0	

Good Condition *** OEM - Original Equipment from the Manufacturer

System operating normally

Spare Tire & Jack

Wiper Blades