

Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive
3350 N. Holland-Sylvania Rd
Toledo, OH 43615

Extended Warrantys Available

12 Month / 15k Mile
24 Month / 30k Mile
36 Month / 36k Mile

Component	Mechanics Evaluation	Update Cost
-----------	----------------------	-------------

Engine

Engine Oil & Filter	Replaced by Herman's Automotive	
Air Filter	Good Condition	
Vacuum Hoses	OEM – But still in very good condition	
Spark Plugs	Good Condition	
Spark Plug Wires	Good Condition	
Ignition Coil	Good Condition	
Engine Mounts	OEM – But still in very good condition	
Engine Management Sensors	OEM – But still in very good condition	
Engine Oil & Filter	Replaced Recently by Previous Owner	
Air Filter	Replaced by Herman's Automotive	28.99
Vacuum Hoses	OEM – But still in very good condition	
Spark Plugs	Good Condition	
Spark Plug Wires	Good Condition	
Ignition Coil	Good Condition	
Engine Mounts	OEM – But still in very good condition	
Engine Management Sensors	OEM – But still in very good condition	
Engine Oil & Filter	Replaced by Herman's Automotive	
Air Filter	Good Condition	
Vacuum Hoses	OEM – But still in very good condition	
Spark Plugs	Good Condition	
Spark Plug Wires	Good Condition	
Ignition Coil	Good Condition	
Engine Mounts	OEM – But still in very good condition	
Engine Management Sensors	OEM – But still in very good condition	

Transmission

Fluid	Fluid is clean and color is normal
Shift Operation	Shift is precise – No apparent slippage
Differential	Not applicable to this vehicle
Clutch	Not applicable to this vehicle
Linkage	Not applicable to this vehicle
4x4 Transfer Case	Not applicable to this vehicle
Fluid	Fluid is clean and color is normal
Shift Operation	Shift is precise – No apparent slippage
Differential	Not applicable to this vehicle
Clutch	Not applicable to this vehicle
Linkage	Not applicable to this vehicle
4x4 Transfer Case	Not applicable to this vehicle
Fluid	Fluid is clean and color is normal
Shift Operation	Shift is precise – No apparent slippage
Differential	Not applicable to this vehicle
Clutch	Not applicable to this vehicle
Linkage	Not applicable to this vehicle
4x4 Transfer Case	Not applicable to this vehicle

Brakes

Front Pads	70-80% of Estimated pad life remaining
Rear Pads/Shoes	70-80% of Estimated pad life remaining
Front Rotors	Good Condition
Rear Rotors/Drums	Good Condition
Brake Calipers	Good Condition
Wheel Cylinders	Good Condition
Wheel Hub Assembly	Good Condition
Master Cylinder	Good Condition
Wheel Speed Sensors	System operating normally
Brake Hoses	Good Condition
Brake Lines	Good Condition
ABS System	System operating normally
Front Pads	70-80% of Estimated pad life remaining
Rear Pads/Shoes	70-80% of Estimated pad life remaining
Front Rotors	Good Condition
Rear Rotors/Drums	Good Condition
Brake Calipers	Good Condition
Wheel Cylinders	Good Condition
Wheel Hub Assembly	Good Condition
Master Cylinder	Good Condition
Wheel Speed Sensors	System operating normally
Brake Hoses	Good Condition
Brake Lines	Good Condition
ABS System	System operating normally

(888) 987-7788
sales@nicecarcompany.com

NICE CAR COMPANY

Completed Updates:

Front Tires	250
Rear Tires	250
Air Filter	28.99
Tire Rotation & Wheel Balance	40.00
Front Tires	250
Rear Tires	250
Vehicle Inspection Fee	50

Total Reconditioning Costs: \$1,118.99

Component	Mechanics Evaluation	Update Cost
-----------	----------------------	-------------

Starting / Charging System

Battery	Good Condition
Starter	System operating normally
Alternator / Regulator	System operating normally
Battery	Good Condition
Starter	System operating normally
Alternator / Regulator	System operating normally
Battery	Good Condition
Starter	System operating normally
Alternator / Regulator	System operating normally

Fuel System

Fuel Tank	System is sound with no apparent leaks
Fuel Lines	System is sound with no apparent leaks
Fuel Filter	Good Condition
Fuel Pump	System operating normally
Fuel Injectors	System operating normally
Fuel Tank	System is sound with no apparent leaks
Fuel Lines	System is sound with no apparent leaks
Fuel Filter	Good Condition
Fuel Pump	System operating normally
Fuel Injectors	System operating normally
Fuel Tank	System is sound with no apparent leaks
Fuel Lines	System is sound with no apparent leaks
Fuel Filter	Good Condition
Fuel Pump	System operating normally
Fuel Injectors	System operating normally

Electrical System

Windshield Wipers	System operating normally
Windshield Washers	System operating normally
Radio	System operating normally
CD Player	Not applicable to this vehicle
Horn	System operating normally
Power Windows	Switches and Motors Operating Normally
Power Locks	Switches and Motors Operating Normally
Power Seat(s)	Switches and Motors Operating Normally
Power Trunk	Switches and Motors Operating Normally
Power Sunroof	Switches and Motors Operating Normally
Power Sliding Door(s)	Switches and Motors Operating Normally
Power Liftgate	System operating normally
Power Mirrors	System operating normally
GPS/Navigation	System operating normally
Backup Camera	System operating normally
Backup Sensors	Not applicable to this vehicle
DVD Entertainment	Not applicable to this vehicle
Cruise Control	System operating normally
Keyless Entry	System operating normally
Head Lights	All Bulbs and switches working properly
Tail Lights	All Bulbs and switches working properly
Brake Lights	All Bulbs and switches working properly
Dimmer Switch	All Bulbs and switches working properly
Turn Signals	All Bulbs and switches working properly
Dash Lights	All Bulbs and switches working properly
Dome Lights	All Bulbs and switches working properly
License Plate Light	All Bulbs and switches working properly
Backup Lights	All Bulbs and switches working properly
Gauges / Indicators	System operating normally
Windshield Wipers	System operating normally
Windshield Washers	System operating normally
Radio	System operating normally
CD Player	Not applicable to this vehicle