## Purchase this vehicle with complete confidence!

Vehicle Certified by Herman's Automotive

Toledo, OH 43615

3350 N. Holland-Sylvania Rd

Extended Warrantys Available

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component Mechanics Evaluation Update Cost

Engine

Engine Management Sensors OEM – But still in very good condition
Engine Mounts OEM – But still in very good condition

Ignition Coil Good Condition
Spark Plug Wires Good Condition

Spark Plug Wires Good Condition
Spark Plugs Good Condition

 Vacuum Hoses
 OEM – But still in very good condition

 Air Filter
 Replaced by Herman's Automotive
 31.99

 Engine Oil & Filter
 Replaced by Herman's Automotive
 39.95

**Transmission** 

4x4 Transfer CaseNot applicable to this vehicleLinkageNot applicable to this vehicleClutchNot applicable to this vehicleDifferentialNot applicable to this vehicle

Shift Operation Shift is precise – No apparent slippage Fluid Fluid is clean and color is normal

**Brakes** 

ABS System System operating normally

Brake Lines Good Condition
Brake Hoses Good Condition

Wheel Speed Sensors System operating normally

Master Cylinder Good Condition
Wheel Hub Assembly Good Condition
Wheel Cylinders Good Condition
Brake Calipers Good Condition
Rear Rotors/Drums Good Condition
Front Rotors Good Condition

Rear Pads/Shoes 70-80% of Estimated pad life remaining Front Pads 70-80% of Estimated pad life remaining

Steering & Suspension

Power Steering Pump OEM – But still in very good condition
Power Steering Rack OEM – But still in very good condition
Springs OEM – But still in very good condition

Ball Joints Good Condition

CV Joints & Boots OEM – But still in very good condition
Universal Joints OEM – But still in very good condition

Outer Tie Rods Good Condition
Inner Tie Rods Good Condition

Rear Struts/Shocks

Front Struts/Shocks

OEM – But still in very good condition

OEM – But still in very good condition

Steering Column

OEM – But still in very good condition

Control Arm Bushings

OEM – But still in very good condition

Stabilizer Bushings

OEM – But still in very good condition

Stabilizer Links

OEM – But still in very good condition

**Exhaust System** 

Tail Pipe OEM – But still in very good condition
Resonator OEM – But still in very good condition
Muffler OEM – But still in very good condition
Catalytic Converter OEM – But still in very good condition
Exhaust Pipe OEM – But still in very good condition

**Heating & Cooling System** 

Air Conditioning System operating normally

Heater Hoses OEM – But still in very good condition

Heater Performance System operating normally Blower Controls System operating normally

Fan OEM – But still in very good condition

Radiator Hoses/Cap Good Condition

Radiator OEM – But still in very good condition
Water Pump OEM – But still in very good condition
Belt Tensioner OEM – But still in very good condition

Belts Good Condition

Antifreeze Fluid is clean and color is normal

(888) 987-7788 sales@nicecarcompany.com

**NICE CAR** COMPANY

**Completed Updates:** 

Tire Rotation & Wheel Balance 40.00
Air Filter 31.99
Engine Oil & Filter 39.95
Vehicle Inspection Fee 50

Total Reconditioning Costs: \$161.94

Component Mechanics Evaluation Update Cost

Starting / Charging System

Alternator / Regulator System operating normally Starter System operating normally

Battery Good Condition

**Fuel System** 

Fuel Injectors System operating normally Fuel Pump System operating normally

Fuel Filter Good Condition

Fuel Lines System is sound with no apparent leaks
Fuel Tank System is sound with no apparent leaks

**Electrical System** 

License Plate Light All Bulbs and switches working properly Dome Lights All Bulbs and switches working properly Dash Lights All Bulbs and switches working properly All Bulbs and switches working properly Turn Signals All Bulbs and switches working properly Dimmer Switch Brake Lights All Bulbs and switches working properly Tail Lights All Bulbs and switches working properly All Bulbs and switches working properly Head Lights

Keyless Entry
Cruise Control
DVD Entertainment
Backup Sensors
Backup Camera

All Builds and switches working p

System operating normally
Not applicable to this vehicle
Bystem operating normally

Not applicable to this vehicle
System operating normally

Backup Camera System operating normally
GPS/Navigation System operating normally
Power Mirrors System operating normally
Power Liftgate Not applicable to this vehicle
Power Sliding Door(s) Not applicable to this vehicle

Power Sunroof Switches and Motors Operating Normally
Power Trunk Switches and Motors Operating Normally
Power Seat(s) Switches and Motors Operating Normally
Power Locks Switches and Motors Operating Normally
Power Windows Switches and Motors Operating Normally

Horn System operating normally
CD Player Not applicable to this vehicle
Radio System operating normally
Windshield Washers System operating normally
Windshield Wipers System operating normally

Backup Lights All Bulbs and switches working properly

Gauges / Indicators System operating normally

Miscellaneous

Wiper Blades Good Condition

Spare Tire & Jack System operating normally Alignment System operating normally

Tire Pressure Normal Condition

Tire Rotation & Wheel Balance Serviced by Herman's Automotive

Rear Tires 70-80% of Tread life remaining Front Tires 70-80% of Tread life remaining

\*\*\* OEM - Original Equipment from the Manufacturer

40.00